

ADA ID: RPRK220202120816

Access Compliance Report Public Rights-of-Way (Curb Ramps)



5

Severity Score:

Main Street: MCFADDEN AVE **Cross Street: MONROE_ST** Location: SE

Initial Pass/Fail: Pass

Codes/Mitigation Info/Possible Solution

Overall Compliance: No



Possible Solutions: Remove & Replace Curb Slope. Remove & Replace Gutter.

Surveyor Notes:

Ramp Type: Type 4 - Parallel

N/A

OC Std/PROW:

R304.2.2, R304.5.4, STD 1115

Total Cost: 504

| Parcel ID Number | 107-362-01 |
|--------------------------|------------|
| Ramp Island Or Median | None |
| Ramp Orientation | Diag |
| Google Street View Link: | |

Street 1 Name MCFADDEN AVE Stop Condition-Street 1 **NoControl** Street 2 Name MONROE_ST Stop Condition-Street 2 StopSign

http://www.google.com/maps/@?api=1&map action=pano&viewpoint=33.73738182,-117.98527457

Obstruction and Utility Measurement/Component Compliance

| Com | pliance Description | Data | Com | pliance Description D | ata |
|-----|------------------------|------|-----|-----------------------|-----|
| Yes | Obstructions Present? | No | N/A | Utilities Present? | No |
| | Obstruction Types | N/A | | Utility Types | |
| | Obstruction Dimensions | N/A | | 1 | N/A |







| Field Measurements/Component Compliance | | | | | | | | |
|---|------------------------|---------------------------------|--------|-----|----------|------------------------|--------|--|
| | Compliance Description | | Data | Com | pliance | Description | Data | |
| | N/A | Ramp Length LT (in) | 90 | N/A | Ramp L | ength RT (in) | 89 | |
| | Yes | Ramp Width LT (in) | 105 | Yes | Ramp W | /idth RT (in) | 105 | |
| | Yes | Ramp Run Slope LT (%) | 6.9 | Yes | Ramp R | un Slope RT (%) | 7.1 | |
| | Yes | Ramp Cross Slope LT (%) | 1.4 | Yes | Ramp C | ross Slope RT (%) | 0.7 | |
| | N/A | Landing Present | Yes | Yes | DWS Pr | ovided | Yes | |
| | N/A | Landing Length (in) | 105 | Yes | DWS Co | ontrast | Yes | |
| | Yes | Landing Width (in) | 48 | Yes | DWS Le | ngth (in) | 36 | |
| | Yes | Landing Run Slope (%) | 2 | Yes | DWS Fu | III Width | Yes | |
| | Yes | Landing Cross Slope (%) | 1 | | DWS Of | fset Type | Single | |
| | N/A | Landing Movement Obstructed? | No | Yes | DWS Of | fset Left (in) | 1 | |
| | | Landing Movement Type | Curb | Yes | DWS Of | fset Right (in) | N/A | |
| | N/A | Landing Shared | No | | | | | |
| | N/A | Clear Space | Yes | | | | | |
| | N/A | Clear Space To Crosswalk (in) | 48 | | | | | |
| 4 | N/A | Marked Crosswalk 1 | No | N/A | Marked | Crosswalk 2 | No | |
| | | Crossing 1 Direction | N | | Crossing | g 2 Direction | W | |
| E | | Marked Crosswalk 1 Width (in) | N/A | | Marked | Crosswalk 2 Width (in) | N/A | |
| l | N/A | Ramp Inside Crosswalk 1 | N/A | N/A | Ramp In | side Crosswalk 2 | N/A | |
| Т | | Crossing 1 Slope (%) | 4.2 | | Crossing | g 2 Slope (%) | 4 | |
| n | | Crossing 1 Cross Slope (%) | 1.3 | | Crossing | g 2 Cross Slope (%) | 0.6 | |
| | Yes | Gutter Ponding | No | No | Curb Slo | рре | 8.9 | |
| | Yes | Gutter Lip Height (in) | 0 | | Road Ru | ın Slope (%) | 0.8 | |
| | No | Gutter Run Slope (%) | 5.2 | | Road Cr | oss Slope (%) | 4.3 | |
| <u>a</u> | Yes | Gutter Cross Slope (%) | 0.4 | Yes | Perpend | licular Joint Present | Yes | |
| 0 | Yes | Overall Surface Condition Accep | ptable | | | | | |
| | | Cross Gutter Present? | No | | Spandre | el Present? | No | |
| A | | Replace Cross Gutter? | N/A | | Replace | e Spandrel? | N/A | |
| | | | | | | | | |