

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: N/A	Cross Street: PUERTO_PL	Location:	<u> </u>
Maria Otara ta NVA	Cross Street: DIEDTO DI	1	_

ADA ID: RPRK220208153054 Ramp	Type: Type 6 - Directional 1	Initial P	ass/F	Fail: Pass Overall Co	omplia	nce:	Yes Severity Score:	2		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	Possible Solutions:		Com	pliance Description	Data	Com	pliance Description	Data		
	M/A		N/A	Ramp Length (in)	120	N/A	Flare Type LT			
			Yes	Ramp Width (in)	70			None		
			Yes	Ramp Run Slope (%)	6	N/A	Flare Slope LT (%)	N/A		
6 A			Yes	Ramp Cross Slope (%)	1.6	N/A	Flare Traversable LT	N/A		
	6		Yes	Grade Break	Yes	Yes	Flare Type RT			
	Surveyor Notes:		Yes	Grade Break Slope (%)	0.3			Curbed2		
\ \	N/A		Yes	Grade Break Cross Slope (%)	1.4	N/A	Flare Slope RT (%)	N/A		
				Addl Para Ramp Left?	No	N/A	Flare Traversable RT	N/A		
// \ . H				Addl Para Ramp Right?	No	Yes	DWS Provided	Yes		
2 2			N/A	Landing Present	Yes	Yes	DWS Contrast	Yes		
6	OC Std/PROW:		Yes	Landing Length (in)	50	Yes	DWS Length (in)	48		
	N/A		Yes	Landing Width (in)	70		DWS Full Width	Yes		
			Yes	Landing Run Slope (%)	0.7		DWS Offset Type	Single		
			Yes	Landing Cross Slope (%)	1.4	Yes	DWS Left Offset (in)	0		
	Total Cost:	\$ 0	N/A	Landing Movement Obstructed?	No	N/A	DWS Right Offset (in)	0		
				Landing Movement Type	N/A					
Parcel ID Number 682-023-0	3 Street 1 Name	N/A	N/A	Landing Shared	Yes					
Ramp Island Or Median Non	e Stop Condition-Street 1	NoControl	N/A	Marked Crosswalk 1	No	N/A	Clear Space	N/A		
Ramp Orientation NonDia	g Street 2 Name	PUERTO_PL		Crossing 1 Direction	s	N/A	Clear Space To Crosswalk (in)	N/A		
Google Street View Link:	Stop Condition-Street 2	N/A		Marked Crosswalk 1 Width (in)	N/A					
http://www.google.com/maps/@?api=1↦_action=pano&viewpoint=3:	6.46208327,-117.6895691 <u>1</u>		N/A	Ramp Inside Crosswalk 1	N/A					
				Crossing 1 Slope (%)	1.4					
Obstruction and Utility Measurement/Component Compliance			Crossing 1 Cross Slope (%)	0.5						
Compliance Description Date		Data	Yes	Gutter Ponding	No	Yes	Curb Slope	0.6		
Yes Obstructions Present?		No	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A		
Obstruction Types N/	1 '''		Yes	Gutter Run Slope (%)	1.1		Road Cross Slope (%)	N/A		
Obstruction Dimensions N/	A	N/A	Yes	Gutter Cross Slope (%)	0.5		Parallel Ramp Side	N/A		
		1	Yes	Overall Surface Condition Acce	eptable	Yes	Perp Joint Present	Yes		
				Cross Gutter Present?	Yes		Spandrel Present?	Yes		

Replace Cross Gutter?

No

Replace Spandrel?

No