

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: DAVENPORT_RD Cross Street: HEDWIG_RD Location: SW

ADA ID: RPRK220217150927 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 14

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R204.3, R304.2.1, R305, STD 1115

Total Cost: \$ 6160

Parcel ID Number	086-583-37
Ramp Island Or Median	None
Ramp Orientation	Diag
Google Street View Link:	

Street 1 Name
DAVENPORT_RD
Stop Condition-Street 1
StopSign
Street 2 Name
HEDWIG_RD
Stop Condition-Street 2
NoControl

http://www.google.com/maps/@?api=1&map action=pano&viewpoint=33.8001136,-118.07264584

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data	Compliance Description	Data
Yes Obstructions Present?	No	N/A Utilities Present?	No
Obstruction Types	N/A	Utility Types	
Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance								
	Compliance Description		Data	Com	pliance	Description	Data	
	N/A	Ramp Length (in)	101	N/A	Flare Ty	pe LT		
	Yes	Ramp Width (in)	60				Sloped	
	Yes	Ramp Run Slope (%)	6.8	N/A	Flare Slo	ppe LT (%)	7.6	
	Yes	Ramp Cross Slope (%)	1.1	N/A	Flare Tra	aversable LT	No	
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT		
	N/A	Landing Length (in)	41				Sloped	
	Yes	Landing Width (in)	60	N/A	Flare Slo	ppe RT (%)	8.1	
	Yes	Landing Run Slope (%)	1.8	N/A	Flare Tra	aversable RT	No	
	Yes	Landing Cross Slope (%)	1	No	DWS Pr	ovided	No	
	N/A	Landing Movement Obstructed?	Yes	N/A	DWS Co	ontrast	N/A	
		Landing Movement Type	Wall	N/A	DWS Le	ngth (in)	N/A	
	N/A	Landing Shared	No	N/A	DWS Fu	ll Width	N/A	
	N/A	Clear Space	Yes	N/A	DWS Of	fset Left (in)	N/A	
	N/A	Clear Space To Crosswalk (in)	48	N/A	DWS Of	fset Right (in)	N/A	
0	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No	
		Crossing 1 Direction	Е		Crossing	g 2 Direction	N	
D		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A	
n	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A	
D		Crossing 1 Slope (%)	3.7		Crossing	g 2 Slope (%)	3.7	
ol		Crossing 1 Cross Slope (%)	0.2		Crossing	g 2 Cross Slope (%)	1	
	Yes	Gutter Ponding	No	Yes	Curb Slo	рре	1.3	
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	0.2	
	Yes	Gutter Run Slope (%)	4.8		Road Cr	oss Slope (%)	2.1	
<u>а</u>	Yes	Gutter Cross Slope (%)	0.9					
0	Yes	s Overall Surface Condition: Accepta		No	Perp Joi	nt Present	No	
		Cross Gutter Present?	No		Spandre	I Present?	No	
Α		Replace Cross Gutter?	N/A		Replace	Spandrel?	N/A	