

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: HEDWIG RD **Cross Street: PEMBERTON RD** Location: SE

ADA ID: RPRK220217160031 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass

Overall Compliance: No

Severity Score:

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Landing.



N/A

OC Std/PROW:

R304.2.1, STD 1115

Total Cost:

531

Parcel ID Number	086-581-01
Ramp Island Or Median	None
Ramp Orientation	Diag
Google Street View Link:	

Street 1 Name HEDWIG_RD Stop Condition-Street 1 StopSign Street 2 Name PEMBERTON_RD Stop Condition-Street 2 **NoControl**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.8000951,-118.07523123

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data Compliance Description	<u>Data</u>
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A



Field Measurements/Component Compliance									
- 1	Compliance Description		Data	Com	pliance Description	Data			
	N/A	Ramp Length (in)	84	N/A	Flare Type LT				
	Yes	Ramp Width (in)	48			Sloped			
	Yes	Ramp Run Slope (%)	7	N/A	Flare Slope LT (%)	10.3			
	Yes	Ramp Cross Slope (%)	0.1	N/A	Flare Traversable LT	No			
	N/A	Landing Present	Yes	N/A	Flare Type RT				
	N/A	Landing Length (in)	48			Sloped			
	Yes	Landing Width (in)	48	N/A	Flare Slope RT (%)	8.2			
	Yes	Landing Run Slope (%)	1.4	N/A	Flare Traversable RT	No			
	Yes	Landing Cross Slope (%)	1.5	Yes	DWS Provided	Yes			
	N/A	Landing Movement Obstructed?	Yes	Yes	DWS Contrast	Yes			
		Landing Movement Type	Wall	Yes	DWS Length (in)	36			
	N/A	Landing Shared	No	Yes	DWS Full Width	Yes			
	N/A	Clear Space	Yes	Yes	DWS Offset Left (in)	0			
	N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Offset Right (in)	N/A			
31	N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No			
		Crossing 1 Direction	N		Crossing 2 Direction	W			
D		Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A			
ın	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A			
D		Crossing 1 Slope (%)	8.0		Crossing 2 Slope (%)	0.4			
ol		Crossing 1 Cross Slope (%)	8.0		Crossing 2 Cross Slope (%)	0.9			
	Yes	Gutter Ponding	No	Yes	Curb Slope	1.9			
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	1.2			
	Yes	Gutter Run Slope (%)	2.2		Road Cross Slope (%)	0.7			
ta_	Yes	Gutter Cross Slope (%)	0.9						
lo	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Joint Present	Yes			
١		Cross Gutter Present?	No		Spandrel Present?	No			
Α		Replace Cross Gutter?	N/A		Replace Spandrel?	N/A			