

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: PUERTO PL Cross Street: PUERTO PL Location: SW ADA ID: RPRK220221144502 Ramp Type:Type 1 - Perpendicular **Initial Pass/Fail: Pass Overall Compliance: No Severity Score:** 16

Codes/Mitigation Info/Possible Solution



Install Detectable Warning System. Remove &

852

Parcel ID Number **682-022-19** Street 1 Name Ramp Island Or Median None Stop Condition-Street 1 Ramp Orientation NonDiag Street 2 Name Google Street View Link: Stop Condition-Street 2

PUERTO PL **NoControl** PUERTO_PL N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.45943119,-117.68987729

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data Compliance Description	Data
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A





Field Measurements/Component Compliance										
	Compliance Description			Com	Compliance Description					
	N/A	Ramp Length (in)	93	N/A	Flare Ty	pe LT				
	Yes	Ramp Width (in)	48				Sloped			
	Yes	Ramp Run Slope (%)	2.2	N/A	Flare Slo	ppe LT (%)	8.3			
	Yes	Ramp Cross Slope (%)	1.2	N/A	Flare Traversable LT		No			
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT				
	N/A	Landing Length (in)	100				Sloped			
	Yes	Landing Width (in)	67	Yes	Flare Slo	ppe RT (%)	5.6			
	Yes	Landing Run Slope (%)	0.7	N/A	Flare Tra	aversable RT	Yes			
	Yes	Landing Cross Slope (%)	0.7	No	DWS Pr	ovided	No			
	N/A	Landing Movement Obstructed?	No	N/A	DWS Co	ontrast	N/A			
		Landing Movement Type	N/A	N/A	DWS Le	ngth (in)	N/A			
	N/A	Landing Shared	No	N/A	DWS Fu	ll Width	N/A			
	N/A	Clear Space	N/A	N/A	DWS Of	fset Left (in)	N/A			
	N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Of	fset Right (in)	N/A			
2	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	N/A			
		Crossing 1 Direction	N		Crossing	2 Direction	N/A			
L		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A			
ol	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A			
L		Crossing 1 Slope (%)	0.6		Crossing	g 2 Slope (%)	N/A			
Α		Crossing 1 Cross Slope (%)	0		Crossing	g 2 Cross Slope (%)	N/A			
	Yes	Gutter Ponding	No	Yes	Curb Slo	рре	0.8			
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	N/A			
_	No	Gutter Run Slope (%)	8.3		Road Cr	oss Slope (%)	N/A			
<u>a</u>	Yes	Gutter Cross Slope (%)	0.1							
0	Yes	es Overall Surface Condition: Accepta		Yes	Perp Joi	nt Present	Yes			
		Cross Gutter Present?	No		Spandre	I Present?	No			
A		Replace Cross Gutter?	N/A		Replace	Spandrel?	N/A			