

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: S_LAURINDA_LN **Cross Street: ROMELLE AVE** Location: NE **Overall Compliance: No** ADA ID: RPRK220222194810 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail **Severity Score:** 16

Codes/Mitigation Info/Possible Solution



Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, STD 1115

Total Cost: 6160

| Parcel ID Number | | Street 1 Name | S_LAURINDA_LN |
|--------------------------|------|-------------------------|---------------|
| Ramp Island Or Median | None | Stop Condition-Street 1 | NoControl |
| Ramp Orientation | Diag | Street 2 Name | ROMELLE_AVE |
| Google Street View Link: | | Stop Condition-Street 2 | NoControl |

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.77557988,-117.82221566

Obstruction and Utility Measurement/Component Compliance

| Com | pliance Description | Data | Com | pliance Description | <u>Data</u> |
|-----|------------------------|------|-----|---------------------|-------------|
| Yes | Obstructions Present? | No | N/A | Utilities Present? | No |
| | Obstruction Types | N/A | | Utility Types | |
| | Obstruction Dimensions | N/A | l | | N/A |



| Field Measurements/Component Compliance | | | | | | | | |
|---|------------------------|----------------------------------|--------|------------------------|-----------|------------------------|------|--|
| | Compliance Description | | Data | Compliance Description | | | Data | |
| | N/A | Ramp Length (in) | 76 | N/A | Flare Ty | pe LT | | |
| | Yes | Ramp Width (in) | 48 | | | | N/A | |
| | No | Ramp Run Slope (%) | 9.2 | N/A | Flare Slo | ppe LT (%) | N/A | |
| | Yes | Ramp Cross Slope (%) | 0.7 | N/A | Flare Tra | aversable LT | N/A | |
| | N/A | Landing Present | N/A | N/A | Flare Ty | pe RT | | |
| | N/A | Landing Length (in) | N/A | | | | N/A | |
| | N/A | Landing Width (in) | N/A | N/A | Flare Slo | ppe RT (%) | N/A | |
| | N/A | Landing Run Slope (%) | N/A | N/A | Flare Tra | aversable RT | N/A | |
| | N/A | Landing Cross Slope (%) | N/A | N/A | DWS Pr | ovided | N/A | |
| | N/A | Landing Movement Obstructed? | N/A | N/A | DWS Co | ontrast | N/A | |
| | | Landing Movement Type | N/A | N/A | DWS Le | ngth (in) | N/A | |
| | N/A | Landing Shared | N/A | N/A | DWS Fu | ll Width | N/A | |
| | N/A | Clear Space | No | N/A | DWS Of | fset Left (in) | N/A | |
| | N/A | Clear Space To Crosswalk (in) | N/A | N/A | DWS Of | fset Right (in) | N/A | |
| 0 | N/A | Marked Crosswalk 1 | No | N/A | Marked | Crosswalk 2 | No | |
| | | Crossing 1 Direction | W | | Crossing | g 2 Direction | s | |
| N | | Marked Crosswalk 1 Width (in) | N/A | | Marked | Crosswalk 2 Width (in) | N/A | |
| ol | N/A | Ramp Inside Crosswalk 1 | N/A | Yes | Ramp In | side Crosswalk 2 | N/A | |
| Ε | | Crossing 1 Slope (%) | 7.2 | | Crossing | g 2 Slope (%) | 5.3 | |
| ol | | Crossing 1 Cross Slope (%) | 0.7 | | Crossing | g 2 Cross Slope (%) | 1.1 | |
| | N/A | Gutter Ponding | N/A | N/A | Curb Slo | рре | 2.1 | |
| | Yes | Gutter Lip Height (in) | 0 | | Road R | un Slope (%) | 0.5 | |
| | N/A | Gutter Run Slope (%) | N/A | | Road Cr | oss Slope (%) | 1.7 | |
| <u>а</u> | N/A | Gutter Cross Slope (%) | N/A | | | | | |
| 0 | Yes | Overall Surface Condition: Accep | otable | Yes | Perp Joi | nt Present | Yes | |
| | | Cross Gutter Present? | Yes | | Spandre | I Present? | Yes | |
| Α | | Replace Cross Gutter? | No | | Replace | Spandrel? | No | |
| | | | | | | | | |