

ADA ID: RPRK220222203131

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: LA_VETA_AVE Cross Street: SWIDLER_PL Location: SE

Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail

Overall Compliance: No

Severity Score: 16

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Grind Gutter Lip.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.5.3, R302.7.2, STD 1115

Total Cost: \$ 6310

	1	1
Parcel ID Number	094-443-01	
Ramp Island Or Median	None	Stop C
Ramp Orientation	Diag	Street
Google Street View Link:		Stop C

1 Street 1 Name LA_VETA_AVE
e Stop Condition-Street 1 StopSign
g Street 2 Name SWIDLER_PL
Stop Condition-Street 2 NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78038097,-117.8143571

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Compliance Description	Data
Yes	Obstructions Present?	No	N/A Utilities Present?	No
	Obstruction Types	N/A	Utility Types	
	Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance								
	Com	Compliance Description		Compliance Description		Data		
	N/A	Ramp Length (in)	72	N/A	Flare Typ	pe LT		
	Yes	Ramp Width (in)	48				N/A	
	No	Ramp Run Slope (%)	8.7	N/A	Flare Slo	pe LT (%)	N/A	
	No	Ramp Cross Slope (%)	4	N/A	Flare Tra	versable LT	N/A	
	N/A	Landing Present	N/A	N/A	Flare Typ	e RT		
	N/A	Landing Length (in)	N/A				N/A	
	N/A	Landing Width (in)	N/A	N/A	Flare Slo	pe RT (%)	N/A	
	N/A	Landing Run Slope (%)	N/A	N/A	Flare Tra	versable RT	N/A	
	N/A	Landing Cross Slope (%)	N/A	N/A	DWS Pro	ovided	N/A	
	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Co	ntrast	N/A	
		Landing Movement Type	N/A	N/A	DWS Lei	ngth (in)	N/A	
	N/A	Landing Shared	N/A	N/A	DWS Fu	l Width	N/A	
	N/A	Clear Space	No	N/A	DWS Off	set Left (in)	N/A	
	N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Off	set Right (in)	N/A	
)	N/A	Marked Crosswalk 1	No	N/A	Marked (Crosswalk 2	No	
		Crossing 1 Direction	N		Crossing	2 Direction	w	
:		Marked Crosswalk 1 Width (in)	N/A		Marked (Crosswalk 2 Width (in)	N/A	
ı	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In:	side Crosswalk 2	N/A	
		Crossing 1 Slope (%)	6.4		Crossing	2 Slope (%)	4.4	
ı		Crossing 1 Cross Slope (%)	5		Crossing	2 Cross Slope (%)	1.2	
	N/A	Gutter Ponding	N/A	N/A	Curb Slo	pe	2.3	
	No	Gutter Lip Height (in)	2.3		Road Ru	ın Slope (%)	4.2	
	N/A	Gutter Run Slope (%)	N/A		Road Cro	oss Slope (%)	7.1	
1	N/A	Gutter Cross Slope (%)	N/A					
)	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Joi	nt Present	Yes	
		Cross Gutter Present?	No		Spandre	Present?	No	
١		Replace Cross Gutter?	N/A		Replace	Spandrel?	N/A	