

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: N/A Cross Street: SENDERO\_WAY Location: NE

ADA ID: RPRK220223181854 Ramp Type:Type 1 - Perpendicular Initial Pass/Fail: Pass Overall Compliance: Yes Severity Score:

## Codes/Mitigation Info/Possible Solution



Possible Solutions:
N/A

Surveyor Notes:

N/A

OC Std/PROW:

N/A

Total Cost:

Cost: \$

Parcel ID Number 741-571-07

Ramp Island Or Median None
Ramp Orientation NonDiag

Google Street View Link:

Street 1 Name N/A
Stop Condition-Street 1 NoControl
Street 2 Name SENDERO\_WAY
Stop Condition-Street 2 N/A

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.52740101,-117.61676299

## **Obstruction and Utility Measurement/Component Compliance**

Compliance Description	Data Compliance Description	Data
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A





Field Measurements/Component Compliance										
	Compliance Description			Com	pliance	Description	Data			
	N/A	Ramp Length (in)	70	N/A	Flare Ty	pe LT				
	Yes	Ramp Width (in)	117				Sloped			
	Yes	Ramp Run Slope (%)	6.3	N/A	Flare Slo	ppe LT (%)	N/A			
	Yes	Ramp Cross Slope (%)	0.8	N/A	Flare Tra	aversable LT	No			
	N/A	Landing Present	Yes	Yes	Flare Ty	pe RT				
	N/A	Landing Length (in)	48				Curbed2			
	Yes	Landing Width (in)	48	N/A	Flare Slo	ppe RT (%)	N/A			
	Yes	Landing Run Slope (%)	0	N/A	Flare Tra	aversable RT	N/A			
	Yes	Landing Cross Slope (%)	2.2	Yes	DWS Pro	ovided	Yes			
	N/A	Landing Movement Obstructed?	No	Yes	DWS Co	ntrast	Yes			
		Landing Movement Type	N/A	Yes	DWS Le	ngth (in)	36			
	N/A	Landing Shared	No	Yes	DWS Fu	ll Width	Yes			
	N/A	Clear Space	N/A	Yes	DWS Of	fset Left (in)	2			
	N/A	Clear Space To Crosswalk (in)	N/A	Yes	DWS Of	fset Right (in)	N/A			
0	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	N/A			
		Crossing 1 Direction	S		Crossing	2 Direction	N/A			
Α		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A			
ol	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A			
Υ		Crossing 1 Slope (%)	1.2		Crossing	g 2 Slope (%)	N/A			
Α		Crossing 1 Cross Slope (%)	2.5		Crossing	2 Cross Slope (%)	N/A			
	Yes	Gutter Ponding	No	Yes	Curb Slo	ppe	0.2			
	Yes	Gutter Lip Height (in)	0		Road Ru	ın Slope (%)	N/A			
	Yes	Gutter Run Slope (%)	1		Road Cr	oss Slope (%)	N/A			
ta	Yes	Gutter Cross Slope (%)	2							
lo	Yes Overall Surface Condition: Accep		otable	Yes	Perp Joi	nt Present	Yes			
		Cross Gutter Present?	Yes		Spandre	l Present?	Yes			
Α		Replace Cross Gutter?	No		Replace	Spandrel?	No			