

#### DEPARTMENT OF TRANSPORTATION

Structure Maintenance & Investigations

Bridge Number : 55C0121

Facility Carried: BREA CANYON BLVD.

Location

: 0.4 MI N/O CENTRAL AVENU

Inspection Date : 10/31/2013

Inspection Type

Routine FC Underwater Special Other

Bridge Inspection Report

STRUCTURE NAME: BREA CANYON CHANNEL

CONSTRUCTION INFORMATION

Year Built : 1920

Year Widened: 1929

Length (m) : 9.1

Skew (degrees):

X

No. of Joints : 0

No. of Hinges :

Structure Description: Continuous 2-span CIP/RC deck slab under 1.5 m of fill with an RC

pier and RC closed end backfilled strutted abutments. Foundation

type is unknown.

Span Configuration

:(S) 2 @ 4.1 m (N) c/c

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN

Inventory Rating: RF=1.00 =>32.4 metric tons

Operating Rating: RF=1.67 =>54.1 metric tons

Calculation Method: LOAD FACTOR Calculation Method: LOAD FACTOR

Permit Rating

: PPPPP

: Type 3: Legal

Type 3S2:Legal

Type 3-3:Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (W) 3.4 m ea, 11 m, 0.9 m ea (E)

Total Width:

Posting Load

17.1 m

Net Width: 11.3 m

No. of Lanes: 2

Speed: 55 mph

Min. Vertical Clearance: Unimpaired

Rail Code: 0000 Rail Description: (E) MBGR (W) None

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth trapezoidal with heavy bushes and trees in the channel bed.

#### INSPECTION COMMENTARY

SCOPE AND ACCESS

There was 2' of stagnant water in span #1 (south) and there was 2.5'of dirt accumulated in span #2 (north); all elements were inspected.

DECK AND ROADWAY

The AC roadway was in fair condition.

SUPERSTRUCTURE

There were no significant defects noted on the superstructure elements.

SUBSTRUCTURE

There is a concrete spall (3 m  $\times$  0.6 m  $\times$  50 mm) at the upstream side of the pier wall in span 1 and delamination area 2 m x 0.5 m at the other face of the pier wall. Probably impacted by debris.

SAFE LOAD CAPACITY

The load rating for this structure is being reviewed by SM&I Rating Branch. An updated Load Rating Summary Sheet will be archived when this review is completed. The current

Printed on: Wednesday 12/18/2013 09:26 AM

55C0121/AAAI/27625

### INSPECTION COMMENTARY

load rating is based on BDS computer output dated 11/21/1979.

ELEMENT INSPECTION RATINGS									
Elem No. Element Description	Env	Total Qty	Unita	Qt	y in eac	h Condi	tion Sta		
	13117	- Och	UIIILS	St. 1	St. 2	St. 3	St. 4	St.	5
39 Concrete Slab - Unprotected w/ AC Overlay	2	156	sq.m.	156	0	0	0		
210 Reinforced Conc Pier Wall	2	17	m.	11	3	3	0		
215 Reinforced Conc Abutment	2	34	m.	34	0	0	0		0
337 Metal Railing (W6X25 Posts)	2	10	m.	10	0	0	0		0

## WORK RECOMMENDATIONS

RecDate: 05/18/2012
Action: Sub-Patch spalls
Work By: LOCAL AGENCY
Status: PROPOSED

EstCost:
StrTarget: 2 YEARS
DistTarget:

Repair the spall and delamination at the north side of the pier wall west face of the wall 3 m  $\times$  0.6 m  $\times$  50 mm spall and at

th

the east face of the wall the delamination area 3 m  $\times$  0.5 m.

RecDate: 06/05/2001 Action : Remove Vegetation Work By: LOCAL AGENCY

Status : PROPOSED

n

EstCost:

EA:

StrTarget:

DistTarget:

Clean the channel to improve the water flow. Remove the bushes and the trees in the channel bed within 30 meters of the

bridge.

CHANNEL X-SECTION			
Side : Upstream Measured From :top of concre	te	-	X-Section Date: 10/31/2013
Location	Horiz(m)	Vert(m)	Comments
Abut 1	0.00	5.00	face of abut wall
	3.20	4.20	
	7.65	2,40	3 3

2 YEARS

Team Leader : \_\_\_ Mikhael T. Zaarour

Report Author : Mikhael T. Zaarour

Inspected By : MT.Zaarour/RR.Morgan

12-18-13

Mikhael T. Zaarour (Registered Civil Engineer)

(Date



# STRUCTURE INVENTORY AND APPRAISAL REPORT

	,
**************************************	**************************************
(O) CONTINUE AND THE	STATUS
(5) INVENTORY ROUTE (ON/UNDER) - ON 140000000	HEALTH INDEX
(2) HIGHERY AGENCY DIGGE	91.1
	PAINT CONDITION INDEX = N/A
(3) COUNTY CODE 059 (4) PLACE CODE 00000	******* CLASSIFICATION ******** CODE
(6) FEATURE INTERSECTED- BREA CANYON CHANNEL	(112) NBIS BRIDGE LENGTH- YES Y
(7) FACILITY CARRIED- BREA CANYON BLVD.	(104) HIGHWAY SYSTEM- NOT ON NHS
(9) LOCATION- 0.4 MI N/O CENTRAL AVENUE	(26) FUNCTIONAL CLASS- MINOR ARTERIAL URBAN . 16
(11) MILEPOINT/KILOMETERPOINT 0	(100) DEFENSE HIGHWAY- NOT STRAHNET 0
(12) BASE HIGHWAY NETWORK- NOT ON NET 0	(101) PARALLEL STRUCTURE- NONE EXISTS N
(13) LRS INVENTORY ROUTE & SUBROUTE	(102) DIRECTION OF TRAFFIC- 2 WAY 2
(16) LATITUDE 33 DEG 56 MIN 16.3 SEC	(103) TEMPORARY STRUCTURE-
(17) LONGITUDE 117 DEG 53 MIN 30 SEC	(105) FED.LANDS HWY- NOT APPLICABLE 0
(98) BORDER BRIDGE STATE CODE % SHARE %	(110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
(99) BORDER BRIDGE STRUCTURE NUMBER	(20) TOLL- ON FREE ROAD
	(21) MAINTAIN- COUNTY HIGHWAY AGENCY 02
****** STRUCTURE TYPE AND MATERIAL ******	(22) OWNER- COUNTY HIGHWAY AGENCY 02
(43) STRUCTURE TYPE MAIN: MATERIAL- CONCRETE	(37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5
TYPE- SLAB CODE 101	
(44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA	******** CONDITION ********* CODE
TYPE- OTHER/NA CODE 000	(58) DECK 7
(45) NUMBER OF SPANS IN MAIN UNIT 2	(59) SUPERSTRUCTURE 7
(46) NUMBER OF APPROACH SPANS 0	(60) SUBSTRUCTURE 6
(107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1	(61) CHANNEL & CHANNEL PROTECTION 8
(108) WEARING SURFACE / PROTECTIVE SYSTEM:	(62) CULVERTS N
	10
D) TYPE OF MEMPRANE STORY	******* LOAD RATING AND POSTING ****** CODE
C) TYPE OF DECK DROWEGETON NOVE	(31) DESIGN LOAD- UNKNOWN 0
CODE 0	(63) OPERATING RATING METHOD- LOAD FACTOR 1
******* AGE AND SERVICE **********	(64) OPERATING RATING- 54.1
(27) YEAR BUILT 1920	(65) INVENTORY RATING METHOD- LOAD FACTOR 1
(106) YEAR RECONSTRUCTED 1929	(66) INVENTORY RATING- 32.4
(42) TYPE OF SERVICE: ON- HIGHWAY 1	(70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
UNDER- WATERWAY 5	(41) STRUCTURE OPEN DOCTED OF GLOCER
(28) LANES:ON STRUCTURE 02 UNDER STRUCTURE 00 (29) AVERAGE DAILY TRAFFIC 19000	DESCRIPTION- OPEN, NO RESTRICTION
23000	
(30) YEAR OF ADT 2009 (109) TRUCK ADT 1 %	******** APPRAISAL ********** CODE
(19) BYPASS, DETOUR LENGTH 2 KM	(67) STRUCTURAL EVALUATION 6
******** GEOMETRIC DATA **********	(68) DECK GEOMETRY
(48) LENGTH OF MAXIMUM SPAN 4.3 M	(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
(49) STRUCTURE LENGTH 9.1 M	(71) WATER ADEQUACY 9
(50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M	(72) APPROACH ROADWAY ALIGNMENT 8
(51) BRIDGE ROADWAY WIDTH CURB TO CURB 11.3 M	(36) TRAFFIC SAFETY FEATURES 0000
(52) DECK WIDTH OUT TO OUT 17.1 M	(113) SCOUR CRITICAL BRIDGES
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 11.0 M	******* PROPOSED IMPROVEMENTS *******
(33) BRIDGE MEDIAN- NO MEDIAN 0	(75) MVDB OB MODY
(34) SKEW 32 DEG (35) STRUCTURE FLARED NO	(75) TYPE OF WORK- CODE
(10) THEFTHORE DOLLARS	(76) LENGTH OF STRUCTURE IMPROVEMENT M
(1-)	(94) BRIDGE IMPROVEMENT COST
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR 8.5 M (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M	(95) ROADWAY IMPROVEMENT COST
(54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M	(96) TOTAL PROJECT COST
(55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M	(97) YEAR OF IMPROVEMENT COST ESTIMATE
(EC) MIN I AM INDERGUARD IM	(114) FUTURE ADT 41217
7.13	(115) YEAR OF FUTURE ADT 2030
********* NAVIGATION DATA *********	**************************************
(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N	
(111) PIER PROTECTION- CODE	(90) INSPECTION DATE 10/13 (91) FREQUENCY 24 MO (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
(39) NAVIGATION VERTICAL CLEARANCE 0.0 M	A \ DD A CONTROL CO. T.
(116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M	A) FRACTURE CRIT DETAIL- NO MO A)
(40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M	B) UNDERWATER INSP- NO MO B)
	C) OTHER SPECIAL INSP- NO MO C)
Tr.	