

Orange County Bridge Review Summary

Dokken Engineering performed a field review of the Orange County bridge listed below in April 2017 to identify maintenance activities eligible for Caltrans' Bridge Preventive Maintenance Program (BPMP), dated December 2015, funding. Additional maintenance activities, if present, not eligible for BPMP funding were also noted. Maintenance recommendations, if noted in the most recent Caltrans Bridge Inspection Report (BIR), were confirmed.

Bridge Number: 55C0573

Bridge Name: Redhill Channel

Year Built: 1980

Facility Carried: Riverford Road

The Redhill Channel culvert at River Road is a reinforced concrete double box culvert. There was no access to the culvert. The culvert was visually inspected from the access roads.

Caltrans BIR recommendations:

- None

Field Inspection Observations

- Vertical cracks on pier nosing.
- There appears to be excessive AC overly. Recommend no addition AC lifts be placed on structure.

Maintenance Needs Assessment

BPMP Assessment

- N/A – No eligible maintenance activities

General Maintenance – Non-BPMP

- Monitor vertical cracks on pier nose. Epoxy inject if increase in size or spalling occurs. Not critical at this time.

Proposed BPMP Construction Costs

- N/A

Construction Items Not Funded by BPMP

- N/A

APPENDIX A

Photos and BIR



Photo 1: Redhill Channel Bridge



Photo 2: Pier Wall



Photo 3: Parapet View



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 55C0573
Facility Carried: RIVERFORD ROAD
Location : 0.1 MI. NW/O BROWNING AV
City :
Inspection Date : 08/05/2015

Bridge Inspection Report

Inspection Type

Routine FC Underwater Special Other

☒

STRUCTURE NAME: REDHILL CHANNEL

CONSTRUCTION INFORMATION

Year Built : 1980 Skew (degrees): 0
Year Widened: 1989 No. of Joints : 0
Length (m) : 6.7 No. of Hinges : 0

Structure Description: Double 3.7 m W and 2.6 m W x 2.4 m H x 14.3 m L RC box culvert
(grade top) beneath 0.6 m of earth fill.

Span Configuration : (W) 2.6 m, 3.7 m (E) clear, normal

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN

Inventory Rating: RF=1.00 =>32.4 metric tons

Calculation Method: FIELD EVAL/ENG JUDGMENT

Operating Rating: RF=1.67 =>54.1 metric tons

Calculation Method: FIELD EVAL/ENG JUDGMENT

Permit Rating : PPPPP

Posting Load : Type 3: Legal

Type 3S2: Legal

Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (S) 0.2 m br, 1.2 m sw, 11.0 m, 1.2 m sw, 0.2 m br (N)

Total Width: 14.8 m Net Width: 11.0 m No. of Lanes: 2 Speed: 25 mph

Min. Vertical Clearance: Unimpaired

Overlay Thickness: 3.0 Inches

Rail Code: 0000

Rail Type	Location	Length (ft)	Rail Modifications
Masonry	Right/Left	64	

DESCRIPTION UNDER STRUCTURE

Channel Description: RC rectangular.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

The inspection was performed by walking on the deck and using the ladder to access under the structure. All elements were visually inspected.

SAFE LOAD CAPACITY

A Load Rating Summary Sheet is included with this bridge inspection report. The current rating has been assigned in accordance with SM&I procedures.

ELEMENT INSPECTION RATINGS AND NOTES

Elem No.	Defect /Prot	Defect	Element Description	Env	Total Qty	Units	Qty in each Condition State			
							St. 1	St. 2	St. 3	St. 4
241			Culvert-RC	2	28	m	28	0	0	0
(241)										
There are 5 hairline vertical cracks in the middle pier wall with white efflorescence.										
331			Railing-RC	2	13	m	13	0	0	0
(331)										
There were no significant defects noted.										

WORK RECOMMENDATIONS - NONE

Team Leader : Mikhael T. Zaarour
 Report Author : Mikhael T. Zaarour
 Inspected By : MT.Zaarour/KD.Henderson

M. KWS 9/23/15
 Mikhael T. Zaarour (Registered Civil Engineer) (Date)



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0573
 (5) INVENTORY ROUTE (ON/UNDER) - ON 140000000
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- REDHILL CHANNEL
 (7) FACILITY CARRIED- RIVERFORD ROAD
 (9) LOCATION- 0.1 MI. NW/O BROWNING AVE
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK- NOT ON NET 0
 (13) LRS INVENTORY ROUTE & SUBROUTE
 (16) LATITUDE 33 DEG 44 MIN 17.15 SEC
 (17) LONGITUDE 117 DEG 48 MIN 08.32 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE
 TYPE- CULVERT CODE 119
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA
 TYPE- OTHER/NA CODE 000
 (45) NUMBER OF SPANS IN MAIN UNIT 2
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE- NOT APPLICABLE CODE N
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- NOT APPLICABLE CODE N
 B) TYPE OF MEMBRANE- NOT APPLICABLE CODE N
 C) TYPE OF DECK PROTECTION- NOT APPLICABLE CODE N

***** AGE AND SERVICE *****

(27) YEAR BUILT 1980
 (106) YEAR RECONSTRUCTED 1989
 (42) TYPE OF SERVICE: ON- HIGHWAY-PEDESTRIAN 5
 UNDER- WATERWAY 5
 (28) LANES:ON STRUCTURE 02 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 1000
 (30) YEAR OF ADT 2009 (109) TRUCK ADT 1 %
 (19) BYPASS, DETOUR LENGTH 2 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 3.7 M
 (49) STRUCTURE LENGTH 6.7 M
 (50) CURB OR SIDEWALK: LEFT 1.2 M RIGHT 1.2 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 11.0 M
 (52) DECK WIDTH OUT TO OUT 14.8 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 11.0 M
 (33) BRIDGE MEDIAN- NO MEDIAN 0
 (34) SKEW 0 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 11.0 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

***** SUFFICIENCY RATING *****

SUFFICIENCY RATING = 96.9

STATUS

HEALTH INDEX 100.0

PAINT CONDITION INDEX = N/A

***** CLASSIFICATION ***** CODE

(112) NBIS BRIDGE LENGTH- YES Y
 (104) HIGHWAY SYSTEM- NOT ON NHS 0
 (26) FUNCTIONAL CLASS- LOCAL URBAN 19
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0
 (101) PARALLEL STRUCTURE- NONE EXISTS N
 (102) DIRECTION OF TRAFFIC- 2 WAY 2
 (103) TEMPORARY STRUCTURE-
 (105) FED.LANDS HWY- NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL- ON FREE ROAD 3
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02
 (22) OWNER- COUNTY HIGHWAY AGENCY 02
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

***** CONDITION ***** CODE

(58) DECK N
 (59) SUPERSTRUCTURE N
 (60) SUBSTRUCTURE N
 (61) CHANNEL & CHANNEL PROTECTION 9
 (62) CULVERTS 8

***** LOAD RATING AND POSTING ***** CODE

(31) DESIGN LOAD- UNKNOWN 0
 (63) OPERATING RATING METHOD- FIELD EVAL/ENG JUD 0
 (64) OPERATING RATING- 54.1
 (65) INVENTORY RATING METHOD- FIELD EVAL/ENG JUL 0
 (66) INVENTORY RATING- 32.4
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A
 DESCRIPTION- OPEN, NO RESTRICTION

***** APPRAISAL ***** CODE

(67) STRUCTURAL EVALUATION 8
 (68) DECK GEOMETRY 7
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 9
 (72) APPROACH ROADWAY ALIGNMENT 8
 (36) TRAFFIC SAFETY FEATURES 0000
 (113) SCOUR CRITICAL BRIDGES 8

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK- CODE
 (76) LENGTH OF STRUCTURE IMPROVEMENT M
 (94) BRIDGE IMPROVEMENT COST
 (95) ROADWAY IMPROVEMENT COST
 (96) TOTAL PROJECT COST
 (97) YEAR OF IMPROVEMENT COST ESTIMATE
 (114) FUTURE ADT 2061
 (115) YEAR OF FUTURE ADT 2032

***** INSPECTIONS *****

(90) INSPECTION DATE 08/15 (91) FREQUENCY 48 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL- NO MO A)
 B) UNDERWATER INSP- NO MO B)
 C) OTHER SPECIAL INSP- NO MO C)