

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: S_OLYMPIA_WAY Cross Street: E_DIXON_AVE Location: NE

ADA ID: RPAT211005085459 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 20

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305, STD 1115

Total Cost: \$ 6160

Parcel ID Number

Ramp Island Or Median

Ramp Orientation

Google Street View Link:

Street 1 Name

Stop Condition-Street 1

Street 2 Name

Stop Condition-Street 2

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.77886359,-117.81567939

Obstruction and Utility Measurement/Component Compliance

Compliance Description Data			Compliance Description	Data
Yes	Obstructions Present?	No	N/A Utilities Present?	No
	Obstruction Types	N/A	Utility Types	
	Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance											
	Com	pliance Description	Data	Com	pliance	Description	Data				
With Two New	N/A	Ramp Length (in)	118	N/A	Flare Ty	pe LT					
ıt.	Yes	Ramp Width (in)	50				Sloped				
	Yes	Ramp Run Slope (%)	6.9	N/A	Flare Slo	ope LT (%)	6.3				
	Yes	Ramp Cross Slope (%)	0.8	N/A	Flare Tra	aversable LT	No				
	N/A	Landing Present	No	N/A	Flare Ty	pe RT					
	N/A	Landing Length (in)	N/A				Sloped				
	No	Landing Width (in)	N/A	N/A	Flare Slo	ope RT (%)	6.1				
	No	Landing Run Slope (%)	N/A	N/A	Flare Tra	aversable RT	No				
	No	Landing Cross Slope (%)	N/A	No	DWS Pr	ovided	No				
	N/A	Landing Movement Obstructed?	No	N/A	DWS Co	ontrast	N/A				
		Landing Movement Type	N/A	N/A	DWS Le	ngth (in)	N/A				
rp, R304.3.2-Para,	N/A	Landing Shared	N/A	N/A	DWS Fu	ll Width	N/A				
	N/A	Clear Space	Yes	N/A	DWS Of	fset Left (in)	N/A				
	N/A	Clear Space To Crosswalk (in)	48	N/A	DWS Of	fset Right (in)	N/A				
\$ 6160	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No				
		Crossing 1 Direction	W		Crossing	g 2 Direction	S				
S_OLYMPIA_WAY		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A				
NoControl	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A				
E_DIXON_AVE		Crossing 1 Slope (%)	3.9		Crossing	g 2 Slope (%)	0.6				
NoControl		Crossing 1 Cross Slope (%)	0.6		Crossing	g 2 Cross Slope (%)	1.2				
	Yes	Gutter Ponding	No	No	Curb Slo	рре	14.6				
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	3				
D-4-	Yes	Gutter Run Slope (%)	0.9		Road Cr	oss Slope (%)	0.1				
Data	Yes	Gutter Cross Slope (%)	0.4								
No	Yes	Overall Surface Condition: Acce	ptable	Yes	Perp Joint Present		Yes				
21/2		Cross Gutter Present?	Yes		Spandre	l Present?	Yes				
N/A		Replace Cross Gutter?	No	l	Replace	Spandrel?	No				