



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



|                                         |                                                                   |                          |                                         |                 |    |
|-----------------------------------------|-------------------------------------------------------------------|--------------------------|-----------------------------------------|-----------------|----|
| Main Street: DEL_REY_DR                 |                                                                   | Cross Street: TIFFANY_PL |                                         | Location:       | E  |
| ADA ID: RPAT211108142855                | Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail |                          | Overall Compliance: No                  | Severity Score: | 15 |
| Codes/Mitigation Info/Possible Solution |                                                                   |                          | Field Measurements/Component Compliance |                 |    |



Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

N/A

OC Std/PROW:

**R304.2.2, STD 1115**

Total Cost: \$ 6160

|                          |            |                         |            |
|--------------------------|------------|-------------------------|------------|
| Parcel ID Number         | 103-212-01 | Street 1 Name           | DEL_REY_DR |
| Ramp Island Or Median    | None       | Stop Condition-Street 1 | NoControl  |
| Ramp Orientation         | Diag       | Street 2 Name           | TIFFANY_PL |
| Google Street View Link: |            | Stop Condition-Street 2 | NoControl  |

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.74378249,-117.80169836](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.74378249,-117.80169836)

## Obstruction and Utility Measurement/Component Compliance

| Compliance | Description            | Data | Compliance | Description        | Data |
|------------|------------------------|------|------------|--------------------|------|
| Yes        | Obstructions Present?  | No   | N/A        | Utilities Present? | No   |
|            | Obstruction Types      | N/A  |            | Utility Types      |      |
|            | Obstruction Dimensions | N/A  |            |                    | N/A  |

| Compliance | Description                           | Data | Compliance | Description                   | Data |
|------------|---------------------------------------|------|------------|-------------------------------|------|
| N/A        | Ramp Length (in)                      | 77   | N/A        | Flare Type LT                 |      |
| Yes        | Ramp Width (in)                       | 48   |            |                               | N/A  |
| No         | Ramp Run Slope (%)                    | 8.7  | N/A        | Flare Slope LT (%)            | N/A  |
| Yes        | Ramp Cross Slope (%)                  | 0.3  | N/A        | Flare Traversable LT          | N/A  |
| N/A        | Landing Present                       | N/A  | N/A        | Flare Type RT                 |      |
| N/A        | Landing Length (in)                   | N/A  |            |                               | N/A  |
| N/A        | Landing Width (in)                    | N/A  | N/A        | Flare Slope RT (%)            | N/A  |
| N/A        | Landing Run Slope (%)                 | N/A  | N/A        | Flare Traversable RT          | N/A  |
| N/A        | Landing Cross Slope (%)               | N/A  | N/A        | DWS Provided                  | N/A  |
| N/A        | Landing Movement Obstructed?          | N/A  | N/A        | DWS Contrast                  | N/A  |
|            | Landing Movement Type                 | N/A  | N/A        | DWS Length (in)               | N/A  |
| N/A        | Landing Shared                        | N/A  | N/A        | DWS Full Width                | N/A  |
| N/A        | Clear Space                           | Yes  | N/A        | DWS Offset Left (in)          | N/A  |
| N/A        | Clear Space To Crosswalk (in)         | N/A  | N/A        | DWS Offset Right (in)         | N/A  |
| N/A        | Marked Crosswalk 1                    | No   | N/A        | Marked Crosswalk 2            | No   |
|            | Crossing 1 Direction                  | NW   |            | Crossing 2 Direction          | SW   |
|            | Marked Crosswalk 1 Width (in)         | N/A  |            | Marked Crosswalk 2 Width (in) | N/A  |
| N/A        | Ramp Inside Crosswalk 1               | N/A  | Yes        | Ramp Inside Crosswalk 2       | N/A  |
|            | Crossing 1 Slope (%)                  | 2.4  |            | Crossing 2 Slope (%)          | 3.8  |
|            | Crossing 1 Cross Slope (%)            | 1.8  |            | Crossing 2 Cross Slope (%)    | 0.2  |
| N/A        | Gutter Ponding                        | N/A  | No         | Curb Slope                    | 6.6  |
| Yes        | Gutter Lip Height (in)                | 0    |            | Road Run Slope (%)            | 1.1  |
| N/A        | Gutter Run Slope (%)                  | N/A  |            | Road Cross Slope (%)          | 0.6  |
| N/A        | Gutter Cross Slope (%)                | N/A  |            |                               |      |
| Yes        | Overall Surface Condition: Acceptable |      | Yes        | Perp Joint Present            | Yes  |
|            | Cross Gutter Present?                 | Yes  |            | Spandrel Present?             | Yes  |
|            | Replace Cross Gutter?                 | No   |            | Replace Spandrel?             | No   |

