

ADA ID: RPRK210924115048

Access Compliance Report Public Rights-of-Way (Curb Ramps)



16

Severity Score:

 Main Street: HARRIET_LN
 Cross Street: AMIES_RD
 Location:
 SE

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, STD 1115

Total Cost: \$ 6160

Parcel ID Number127-401-18Street 1 NameHARRIET_LNRamp Island Or MedianNoneStop Condition-Street 1NoControlRamp OrientationDiagStreet 2 NameAMIES_RDGoogle Street View Link:Stop Condition-Street 2NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.81178524,-117.96472646

Obstruction and Utility Measurement/Component Compliance

Compliance Description Data		Compliance Description	Data	
Yes	Obstructions Present?	No	N/A Utilities Present?	No
	Obstruction Types	N/A	Utility Types	
	Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance									
1	Com	Compliance Description		Com	pliance Description	Data			
	N/A	Ramp Length (in)	50	N/A	Flare Type LT				
	Yes	Ramp Width (in)	48			N/A			
	No	Ramp Run Slope (%)	10	N/A	Flare Slope LT (%)	N/A			
	Yes	Ramp Cross Slope (%)	0.9	N/A	Flare Traversable LT	N/A			
	N/A	Landing Present	N/A	N/A	Flare Type RT				
	N/A	Landing Length (in)	N/A			N/A			
	N/A	Landing Width (in)	N/A	N/A	Flare Slope RT (%)	N/A			
	N/A	Landing Run Slope (%)	N/A	N/A	Flare Traversable RT	N/A			
	N/A	Landing Cross Slope (%)	N/A	N/A	DWS Provided	N/A			
	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Contrast	N/A			
		Landing Movement Type	N/A	N/A	DWS Length (in)	N/A			
	N/A	Landing Shared	N/A	N/A	DWS Full Width	N/A			
	N/A	Clear Space	Yes	N/A	DWS Offset Left (in)	N/A			
	N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Offset Right (in)	N/A			
)	N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No			
		Crossing 1 Direction	N		Crossing 2 Direction	W			
ı		Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A			
ı	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A			
)		Crossing 1 Slope (%)	0.2		Crossing 2 Slope (%)	4.3			
ı		Crossing 1 Cross Slope (%)	6.2		Crossing 2 Cross Slope (%)	0.9			
	N/A	Gutter Ponding	N/A	N/A	Curb Slope	3.9			
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	0.4			
	N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	0.5			
-	N/A	Gutter Cross Slope (%)	N/A						
'	Yes Overall Surface Condition: Accep		otable	Yes	Perp Joint Present	Yes			
		Cross Gutter Present?	Yes		Spandrel Present?	Yes			
۱ ا		Replace Cross Gutter?	No	I	Replace Spandrel?	No			

Overall Compliance: No