

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



NE

Main Street: S WOODLAND ST

**Cross Street: E FAIRHAVEN AVE** 

Location:

ADA ID: RPRK211007113944

Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail

**Overall Compliance: No** 

**Severity Score:** 

## **Codes/Mitigation Info/Possible Solution**

Possible Solutions:

Remove & Replace Curb Ramp With Two New **Directional Ramps or Equivalent.** 

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, STD 1115

Total Cost:

6160

| Parcel ID Number         |      | Street 1 Name           |
|--------------------------|------|-------------------------|
| Ramp Island Or Median    | None | Stop Condition-Street 1 |
| Ramp Orientation         | Diag | Street 2 Name           |
| Google Street View Link: |      | Stop Condition-Street 2 |

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.77362203,-117.81293978

## **Obstruction and Utility Measurement/Component Compliance**

| Compliance Description    | -   | Compliance Description | Data |
|---------------------------|-----|------------------------|------|
| Yes Obstructions Present? | No  | N/A Utilities Present? | No   |
| Obstruction Types         | N/A | Utility Types          |      |
| Obstruction Dimensions    | N/A |                        | N/A  |



| Field Measurements/Component Compliance |     |                                  |        |     |                               |        |  |
|---|-----|----------------------------------|--------|-----|-------------------------------|--------|--|
|   | Com | pliance Description              | Data   | Com | pliance Description           | Data   |  |
| p With Two New                          | N/A | Ramp Length (in)                 | 89     | N/A | Flare Type LT                 |        |  |
| ent.                                    | Yes | Ramp Width (in)                  | 48     |     |                               | Sloped |  |
|   | Yes | Ramp Run Slope (%)               | 6.6    | N/A | Flare Slope LT (%)            | 10     |  |
|   | Yes | Ramp Cross Slope (%)             | 1.2    | N/A | Flare Traversable LT          | No     |  |
|   | N/A | Landing Present                  | No     | N/A | Flare Type RT                 |        |  |
|   | N/A | Landing Length (in)              | N/A    |     |                               | Sloped |  |
|   | N/A | Landing Width (in)               | N/A    | N/A | Flare Slope RT (%)            | 9.7    |  |
|   | N/A | Landing Run Slope (%)            | N/A    | N/A | Flare Traversable RT          | No     |  |
|   | N/A | Landing Cross Slope (%)          | N/A    | N/A | DWS Provided                  | Yes    |  |
|   | N/A | Landing Movement Obstructed?     | No     | N/A | DWS Contrast                  | Yes    |  |
|   |     | Landing Movement Type            | N/A    | N/A | DWS Length (in)               | 36     |  |
|   | N/A | Landing Shared                   | N/A    | N/A | DWS Full Width                | Yes    |  |
|   | N/A | Clear Space                      | Yes    | N/A | DWS Offset Left (in)          | 0      |  |
|   | N/A | Clear Space To Crosswalk (in)    | N/A    | N/A | DWS Offset Right (in)         | N/A    |  |
| \$ 6160                                 | N/A | Marked Crosswalk 1               | No     | N/A | Marked Crosswalk 2            | No     |  |
|   |     | Crossing 1 Direction             | W      |     | Crossing 2 Direction          | S      |  |
| S_WOODLAND_ST                           |     | Marked Crosswalk 1 Width (in)    | N/A    |     | Marked Crosswalk 2 Width (in) | N/A    |  |
| StopSign                                | N/A | Ramp Inside Crosswalk 1          | N/A    | Yes | Ramp Inside Crosswalk 2       | N/A    |  |
| E_FAIRHAVEN_AVE                         |     | Crossing 1 Slope (%)             | 6.8    |     | Crossing 2 Slope (%)          | 3.2    |  |
| NoControl                               |     | Crossing 1 Cross Slope (%)       | 1.1    |     | Crossing 2 Cross Slope (%)    | 0.7    |  |
|   | N/A | Gutter Ponding                   | No     | No  | Curb Slope                    | 13.7   |  |
|   | Yes | Gutter Lip Height (in)           | 0      |     | Road Run Slope (%)            | 5.9    |  |
| •                                       | N/A | Gutter Run Slope (%)             | 7.3    |     | Road Cross Slope (%)          | 1      |  |
| Data                                    | N/A | Gutter Cross Slope (%)           | 1.4    |     |                               |        |  |
| No                                      | Yes | Overall Surface Condition: Accep | otable | Yes | Perp Joint Present            | Yes    |  |
|   |     | Cross Gutter Present?            | Yes    |     | Spandrel Present?             | Yes    |  |
| N/A                                     |     | Replace Cross Gutter?            | No     |     | Replace Spandrel?             | No     |  |
|   |     |                                  |        |     |                               |        |  |