

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: THORNHILL ST **Cross Street: BENJAMIN DR** Location: ADA ID: RPRK211020135432 Ramp Type: Blended Transition 2 Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 30

Codes/Mitigation Info/Possible Solution



Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R204.3, R304.5.3, STD 1115

Total Cost: 3080

Parcel ID Number	759-152-11	Street 1 Name	THORNHILL_ST
Ramp Island Or Median	None	Stop Condition-Street 1	StopSign
Ramp Orientation	Diag	Street 2 Name	BENJAMIN_DR
Google Street View Link:		Stop Condition-Street 2	NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.57489933,-117.63490025

Obstruction and Utility Measurement/Component Compliance

Compliance D	escription	Data	Com	pliance	Description	Data	l
Yes Obstruction	ns Present?	No	N/A	Utilities I	Present?	No	l
Obstruction	n Types	N/A		Utility Ty	pes		l
Obstruction	n Dimensions	N/A	J			N/A	l







Field Measurements/Component Compliance							
	Com	pliance Description	Data	Com	pliance Description	Data	
	N/A	Ramp Length (in)	118	N/A	Flare Slope LT (%)	N/A	
	Yes	Ramp Width (in)	87	N/A	Flare Traversable LT	N/A	
	Yes	Ramp Run Slope (%)	5	N/A	Flare Slope RT (%)	N/A	
	No	Ramp Cross Slope (%)	9.6	N/A	Flare Traversable RT	N/A	
	N/A	Landing Present	N/A	N/A	DWS Provided	N/A	
	N/A	Landing Length (in)	N/A	N/A	DWS Contrast	N/A	
	N/A	Landing Width (in)	N/A	N/A	DWS Length (in)	N/A	
	N/A	Landing Run Slope (%)	N/A	N/A	DWS Full Width	N/A	
	N/A	Landing Cross Slope (%)	N/A		DWS Offset Type	N/A	
	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Offset Left (in)	N/A	
		Landing Movement Type	N/A	N/A	DWS Offset Right (in)	N/A	
	N/A	Landing Shared	N/A				
	N/A	Clear Space	Yes				
	N/A	Clear Space To Crosswalk (in)	N/A				
0	N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No	
		Crossing 1 Direction	Е		Crossing 2 Direction	N	
Т		Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A	
n	N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	N/A	
R		Crossing 1 Slope (%)	6.5		Crossing 2 Slope (%)	5.1	
ol		Crossing 1 Cross Slope (%)	1.9		Crossing 2 Cross Slope (%)	11.2	
	N/A	Gutter Ponding	N/A	N/A	Curb Slope	0.4	
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	6.5	
_	N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	2	
a	N/A	Gutter Cross Slope (%)	N/A				
0	Yes	Overall Surface Condition Accep	ptable				
		Cross Gutter Present?	No		Spandrel Present?	No	
Α		Replace Cross Gutter?	N/A		Replace Spandrel?	N/A	