

Access Compliance Report Public Rights-of-Way (Curb Ramps)



25

Main Street: CLYDESDALE DR **Cross Street: TALBOTT CT** Location:

ADA ID: RPRK211112121449 Ramp Type: Type 4 - Parallel **Initial Pass/Fail: Pass Overall Compliance: No Severity Score:**

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R204.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305, R304.5.4, STD 1115

Total Cost: 4252

Parcel ID Number		Street 1 Name
Ramp Island Or Median	None	Stop Condition-Street 1
Ramp Orientation	Diag	Street 2 Name
Google Street View Link:		Stop Condition-Street 2

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.54871223,-117.63979408

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data Compliance Description	Data
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A



Field Measurements/Component Compliance								
	Com	pliance Description	Data	Com	pliance Description	Data		
With Two New	N/A	Ramp Length LT (in)	124	N/A	Ramp Length RT (in)	132		
nt. Remove &	Yes	Ramp Width LT (in)	54	Yes	Ramp Width RT (in)	54		
	Yes	Ramp Run Slope LT (%)	7.7	Yes	Ramp Run Slope RT (%)	3.5		
	Yes	Ramp Cross Slope LT (%)	0.5	Yes	Ramp Cross Slope RT (%)	1.1		
	N/A	Landing Present	No	No	DWS Provided	No		
	N/A	Landing Length (in)	N/A	N/A	DWS Contrast	N/A		
	No	Landing Width (in)	N/A	N/A	DWS Length (in)	N/A		
	No	Landing Run Slope (%)	N/A	N/A	DWS Full Width	N/A		
	No	Landing Cross Slope (%)	N/A		DWS Offset Type	N/A		
	N/A	Landing Movement Obstructed?	? No	N/A	DWS Offset Left (in)	N/A		
		Landing Movement Type	Curb	N/A	DWS Offset Right (in)	N/A		
)4.2.2-Perp,	N/A	Landing Shared	N/A					
R304.5.4, STD N	N/A	Clear Space	Yes					
	N/A	Clear Space To Crosswalk (in)	48					
\$ 4252	N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No		
		Crossing 1 Direction	NW		Crossing 2 Direction	SW		
CLYDESDALE_DR		Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A		
NoControl	N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	N/A		
TALBOTT_CT		Crossing 1 Slope (%)	1.1		Crossing 2 Slope (%)	0.5		
NoControl		Crossing 1 Cross Slope (%)	3		Crossing 2 Cross Slope (%)	0.9		
	Yes	Gutter Ponding	No	No	Curb Slope	11.4		
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	0.3		
Data	No	Gutter Run Slope (%)	6.9		Road Cross Slope (%)	4.2		
Data	Yes	Gutter Cross Slope (%)	1.2	No	Perpendicular Joint Present	No		
No	Yes	Overall Surface Condition Acc	eptable					
****		Cross Gutter Present?	No		Spandrel Present?	No		
N/A		Replace Cross Gutter?	N/A		Replace Spandrel?	N/A		