

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: MONTECITO RD **Cross Street: TUCKER LN** Location: SW ADA ID: RPRK211208113335 Ramp Type: Type 4 - Parallel Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 30

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R204.3, R304.5.3, STD 1115

Total Cost: 4000

Parcel ID Number 086-162-21 Ramp Island Or Median None Ramp Orientation Diag Google Street View Link:

Street 1 Name MONTECITO RD Stop Condition-Street 1 **NoControl** Street 2 Name **TUCKER LN** Stop Condition-Street 2 StopSign

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78375142,-118.07639309

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data Compliance Description	Data
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A



Field Measurements/Component Compliance									
	Com	pliance Description	Data	Com	pliance Description	Data			
	N/A	Ramp Length LT (in)	114	N/A	Ramp Length RT (in)	105			
	Yes	Ramp Width LT (in)	110	Yes	Ramp Width RT (in)	110			
	Yes	Ramp Run Slope LT (%)	1	Yes	Ramp Run Slope RT (%)	7.4			
	No	Ramp Cross Slope LT (%)	3.7	No	Ramp Cross Slope RT (%)	7.6			
	N/A	Landing Present	N/A	N/A	DWS Provided	N/A			
	N/A	Landing Length (in)	N/A	N/A	DWS Contrast	N/A			
	N/A	Landing Width (in)	N/A	N/A	DWS Length (in)	N/A			
	N/A	Landing Run Slope (%)	N/A	N/A	DWS Full Width	N/A			
	N/A	Landing Cross Slope (%)	N/A		DWS Offset Type	N/A			
	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Offset Left (in)	N/A			
		Landing Movement Type	N/A	N/A	DWS Offset Right (in)	N/A			
	N/A	Landing Shared	N/A						
	N/A	Clear Space	Yes						
	N/A	Clear Space To Crosswalk (in)	N/A						
0	N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	Yes			
		Crossing 1 Direction	Е		Crossing 2 Direction	N			
D		Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	144			
ol	N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	Yes			
N		Crossing 1 Slope (%)	7.8		Crossing 2 Slope (%)	2.8			
n		Crossing 1 Cross Slope (%)	2.9		Crossing 2 Cross Slope (%)	2.4			
	N/A	Gutter Ponding	N/A	N/A	Curb Slope	0.5			
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	3.2			
	N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	1.9			
a	N/A	Gutter Cross Slope (%)	N/A	No	Perpendicular Joint Present	No			
0	Yes	Overall Surface Condition Accept							
		Cross Gutter Present?	Yes		Spandrel Present?	Yes			
Α		Replace Cross Gutter?	No		Replace Spandrel?	No			
	1								