

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Main Street: IMPALA DR **Cross Street: HOLT AVE** Location: NW

ADA ID: RPRK220124114151 Ramp Type: Type 4 - Parallel Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 

## **Codes/Mitigation Info/Possible Solution**



Possible Solutions: Remove & Replace Curb Ramp With Two New **Directional Ramps or Equivalent.** 

Surveyor Notes:

N/A

OC Std/PROW:

R304.5.3, STD 1115

Total Cost: 4000

Parcel ID Number	401-441-04	Street 1 Name	IMPALA_DR
Ramp Island Or Median	None	Stop Condition-Street 1	StopSign
Ramp Orientation	Diag	Street 2 Name	HOLT_AVE
Google Street View Link:		Stop Condition-Street 2	NoControl

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.75904373,-117.81449762

## **Obstruction and Utility Measurement/Component Compliance**

Com	pliance Description	Data	Com	pliance Description [	Data_
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A	J		N/A



Field Measurements/Component Compliance								
	Com	pliance Description	Data	Com	pliance	Description	Data	
	N/A	Ramp Length LT (in)	87	N/A	Ramp L	ength RT (in)	88	
	Yes	Ramp Width LT (in)	87	Yes	Ramp V	/idth RT (in)	87	
	Yes	Ramp Run Slope LT (%)	4.8	Yes	Ramp R	un Slope RT (%)	6.1	
	No	Ramp Cross Slope LT (%)	2.6	Yes	Ramp C	ross Slope RT (%)	0.7	
	N/A	Landing Present	N/A	N/A	DWS Pr	rovided	N/A	
	N/A	Landing Length (in)	N/A	N/A	DWS Co	ontrast	N/A	
	N/A	Landing Width (in)	N/A	N/A	DWS Le	ength (in)	N/A	
	N/A	Landing Run Slope (%)	N/A	N/A	DWS Fu	ıll Width	N/A	
	N/A	Landing Cross Slope (%)	N/A		DWS Of	fset Type	N/A	
	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Of	ffset Left (in)	N/A	
		Landing Movement Type	N/A	N/A	DWS Of	ffset Right (in)	N/A	
	N/A	Landing Shared	N/A					
	N/A	Clear Space	Yes					
	N/A	Clear Space To Crosswalk (in)	N/A					
0	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No	
		Crossing 1 Direction	S		Crossing	g 2 Direction	E	
R		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A	
n	N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Ir	nside Crosswalk 2	N/A	
Ε		Crossing 1 Slope (%)	5.2		Crossing	g 2 Slope (%)	8	
ol		Crossing 1 Cross Slope (%)	2.7		Crossing	g 2 Cross Slope (%)	0.6	
	N/A	Gutter Ponding	N/A	Yes	Curb Slo	ope	0.6	
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	0.3	
	N/A	Gutter Run Slope (%)	N/A		Road Ci	ross Slope (%)	2.2	
a	N/A	Gutter Cross Slope (%)	N/A	Yes	Perpend	licular Joint Present	Yes	
0	Yes	Overall Surface Condition Accep	otable					
		Cross Gutter Present?	Yes		Spandr	el Present?	Yes	
Α		Replace Cross Gutter?	No		Replace	e Spandrel?	No	
	l							