



☒ show 'to align' entities r = 20.000 RMS < 10%

	X	Y	Z	Error	
A0	409.577266	845.486399	-8.592849	1.38667	<input checked="" type="checkbox"/>
A1	-3.885719	169.873392	-0.634849	7.25255	<input checked="" type="checkbox"/>
A2	-137.238713	19.208391	0.064151	5.23576	<input checked="" type="checkbox"/>
A3	-193.198720	48.082392	-2.954849	4.50007	<input checked="" type="checkbox"/>

☒ show 'reference' entities

	X	Y	Z	Error	
R0	6078143.806...	2262966.454...	236.731995	1.38667	<input checked="" type="checkbox"/>
R1	6075549.068...	2262988.430...	230.126999	7.25255	<input checked="" type="checkbox"/>
R2	6074900.952...	2263120.309...	234.481003	5.23576	<input checked="" type="checkbox"/>
R3	6074882.446...	2263325.929...	224.794006	4.50007	<input checked="" type="checkbox"/>

☒ adjust scale Rotation XYZ ☒ Tx ☒ Ty ☒ Tz

☐ auto update zoom align reset ☒ ☒

Error in feet

Final RMS: 5.05436

-----

Transformation matrix

1.680 2.816 -0.038 -3025.103

-2.816 1.679 -0.084 -201.079

-0.053 0.076 3.278 222.099

0.000 0.000 0.000 1.000

-----

Scale: 3.27944 (already integrated in above matrix!)

-----

Refer to Console (F8) for more details

OK

