Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Main Street: IRVINE_AVE | **Cross Street: MESA_DR** | **Location: SW**

ADA ID: RPAT220128133627 | **Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail** | **Overall Compliance: No** | **Severity Score: 2**

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.5.3, STD 1115

Total Cost: **$ 6160**

Parcel ID Number	**000**	Street 1 Name	**IRVINE_AVE**
Ramp Island Or Median	**None**	Stop Condition-Street 1	**Signal**
Ramp Orientation	**Diag**	Street 2 Name	**MESA_DR**
Google Street View Link:		Stop Condition-Street 2	**Signal**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.65846295,-117.8842441

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	**No**	**N/A**	Utilities Present?	**No**
	Obstruction Types	**N/A**		Utility Types	
	Obstruction Dimensions	**N/A**			**N/A**

Field Measurements/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	**109**	**N/A**	Flare Type LT	
Yes	Ramp Width (in)	**50**			**N/A**
Yes	Ramp Run Slope (%)	**6.3**	**N/A**	Flare Slope LT (%)	**N/A**
No	Ramp Cross Slope (%)	**2.9**	**N/A**	Flare Traversable LT	**N/A**
N/A	Landing Present	**N/A**	**N/A**	Flare Type RT	
N/A	Landing Length (in)	**N/A**			**N/A**
N/A	Landing Width (in)	**N/A**	**N/A**	Flare Slope RT (%)	**N/A**
N/A	Landing Run Slope (%)	**N/A**	**N/A**	Flare Traversable RT	**N/A**
N/A	Landing Cross Slope (%)	**N/A**	**N/A**	DWS Provided	**N/A**
N/A	Landing Movement Obstructed?	**N/A**	**N/A**	DWS Contrast	**N/A**
	Landing Movement Type	**N/A**	**N/A**	DWS Length (in)	**N/A**
N/A	Landing Shared	**N/A**	**N/A**	DWS Full Width	**N/A**
N/A	Clear Space	**Yes**	**N/A**	DWS Offset Left (in)	**N/A**
N/A	Clear Space To Crosswalk (in)	**48**	**N/A**	DWS Offset Right (in)	**N/A**
N/A	Marked Crosswalk 1	**Yes**	**N/A**	Marked Crosswalk 2	**Yes**
	Crossing 1 Direction	**E**		Crossing 2 Direction	**N**
	Marked Crosswalk 1 Width (in)	**118**		Marked Crosswalk 2 Width (in)	**118**
N/A	Ramp Inside Crosswalk 1	**Yes**	**Yes**	Ramp Inside Crosswalk 2	**Yes**
	Crossing 1 Slope (%)	**4.47**		Crossing 2 Slope (%)	**1.64**
	Crossing 1 Cross Slope (%)	**1.99**		Crossing 2 Cross Slope (%)	**4.82**
N/A	Gutter Ponding	**N/A**	**N/A**	Curb Slope	**2.1**
Yes	Gutter Lip Height (in)	**0**		Road Run Slope (%)	**2.08**
N/A	Gutter Run Slope (%)	**N/A**		Road Cross Slope (%)	**4.02**
N/A	Gutter Cross Slope (%)	**N/A**			
Yes	Overall Surface Condition: **Acceptable**		**Yes**	Perp Joint Present	**Yes**
	Cross Gutter Present?	**No**		Spandrel Present?	**No**
	Replace Cross Gutter?	**N/A**		Replace Spandrel?	**N/A**