Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Main Street: N/A | **Cross Street: OSO_PKWY** | **Location: NE**

ADA ID: RPRK211021115804 | **Ramp Type:Type 1 - Perpendicular** | **Initial Pass/Fail: Pass** | **Overall Compliance: No** | **Severity Score: 8**

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Landing.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.1, R304.5.3, STD 1115

Total Cost: **$ 531**

Parcel ID Number	**125-099-90**	Street 1 Name	**N/A**
Ramp Island Or Median	**None**	Stop Condition-Street 1	**Signal**
Ramp Orientation	**NonDiag**	Street 2 Name	**OSO_PKWY**
Google Street View Link:		Stop Condition-Street 2	**N/A**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.58698002,-117.61110723

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	**No**	**N/A**	Utilities Present?	**No**
	Obstruction Types	**N/A**		Utility Types	
	Obstruction Dimensions	**N/A**			**N/A**

Field Measurements/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	**109**	**Yes**	Flare Type LT	
Yes	Ramp Width (in)	**48**			**Curbed2**
Yes	Ramp Run Slope (%)	**7**	**N/A**	Flare Slope LT (%)	**N/A**
Yes	Ramp Cross Slope (%)	**1.3**	**N/A**	Flare Traversable LT	**N/A**
N/A	Landing Present	**Yes**	**N/A**	Flare Type RT	
N/A	Landing Length (in)	**29**			**Sloped**
Yes	Landing Width (in)	**48**	**Yes**	Flare Slope RT (%)	**5.6**
Yes	Landing Run Slope (%)	**1.9**	**N/A**	Flare Traversable RT	**Yes**
No	Landing Cross Slope (%)	**2.3**	**Yes**	DWS Provided	**Yes**
N/A	Landing Movement Obstructed?	**No**	**Yes**	DWS Contrast	**Yes**
	Landing Movement Type	**N/A**	**Yes**	DWS Length (in)	**36**
N/A	Landing Shared	**No**	**Yes**	DWS Full Width	**Yes**
N/A	Clear Space	**N/A**	**Yes**	DWS Offset Left (in)	**0**
N/A	Clear Space To Crosswalk (in)	**N/A**	**Yes**	DWS Offset Right (in)	**N/A**
N/A	Marked Crosswalk 1	**Yes**	**N/A**	Marked Crosswalk 2	**N/A**
	Crossing 1 Direction	**W**		Crossing 2 Direction	**N/A**
	Marked Crosswalk 1 Width (in)	**144**		Marked Crosswalk 2 Width (in)	**N/A**
Yes	Ramp Inside Crosswalk 1	**Yes**	**Yes**	Ramp Inside Crosswalk 2	**N/A**
	Crossing 1 Slope (%)	**0.9**		Crossing 2 Slope (%)	**N/A**
	Crossing 1 Cross Slope (%)	**0.7**		Crossing 2 Cross Slope (%)	**N/A**
Yes	Gutter Ponding	**No**	**Yes**	Curb Slope	**3.9**
Yes	Gutter Lip Height (in)	**0**		Road Run Slope (%)	**N/A**
Yes	Gutter Run Slope (%)	**1.6**		Road Cross Slope (%)	**N/A**
Yes	Gutter Cross Slope (%)	**0.4**			
Yes	Overall Surface Condition:	**Acceptable**	**Yes**	Perp Joint Present	**Yes**
	Cross Gutter Present?	**No**		Spandrel Present?	**Yes**
	Replace Cross Gutter?	**N/A**		Replace Spandrel?	**N/A**