Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Main Street: TIERNO_RD | **Cross Street: ANDAZA_ST** | **Location: S**

ADA ID: RPRK211129125208 | **Ramp Type:Type 1 - Perpendicular** | **Initial Pass/Fail: Pass** | **Overall Compliance: No** | **Severity Score: 2**

Codes/Mitigation Info/Possible Solution

Possible Solutions:

Remove & Replace Curb Slope.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, STD 1115

Total Cost: **$ 252**

Parcel ID Number	**755-321-02**	Street 1 Name	**TIERNO_RD**
Ramp Island Or Median	**None**	Stop Condition-Street 1	**NoControl**
Ramp Orientation	**NonDiag**	Street 2 Name	**ANDAZA_ST**
Google Street View Link:		Stop Condition-Street 2	**N/A**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.53430686,-117.59974521

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	**No**	**N/A**	Utilities Present?	**No**
	Obstruction Types	**N/A**		Utility Types	
	Obstruction Dimensions	**N/A**			**N/A**




Field Measurements/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	**84**	**N/A**	Flare Type LT	
Yes	Ramp Width (in)	**60**			**Sloped**
Yes	Ramp Run Slope (%)	**5.4**	**N/A**	Flare Slope LT (%)	**10.3**
Yes	Ramp Cross Slope (%)	**1.5**	**N/A**	Flare Traversable LT	**No**
N/A	Landing Present	**Yes**	**N/A**	Flare Type RT	
N/A	Landing Length (in)	**72**			**Sloped**
Yes	Landing Width (in)	**72**	**N/A**	Flare Slope RT (%)	**10.8**
Yes	Landing Run Slope (%)	**0**	**N/A**	Flare Traversable RT	**No**
Yes	Landing Cross Slope (%)	**1**	**Yes**	DWS Provided	**Yes**
N/A	Landing Movement Obstructed?	**No**	**Yes**	DWS Contrast	**Yes**
	Landing Movement Type	**N/A**	**Yes**	DWS Length (in)	**36**
N/A	Landing Shared	**No**	**Yes**	DWS Full Width	**Yes**
N/A	Clear Space	**N/A**	**Yes**	DWS Offset Left (in)	**0**
N/A	Clear Space To Crosswalk (in)	**N/A**	**Yes**	DWS Offset Right (in)	**N/A**
N/A	Marked Crosswalk 1	**Yes**	**N/A**	Marked Crosswalk 2	**N/A**
	Crossing 1 Direction	**NE**		Crossing 2 Direction	**N/A**
	Marked Crosswalk 1 Width (in)	**144**		Marked Crosswalk 2 Width (in)	**N/A**
Yes	Ramp Inside Crosswalk 1	**Yes**	**Yes**	Ramp Inside Crosswalk 2	**N/A**
	Crossing 1 Slope (%)	**3.8**		Crossing 2 Slope (%)	**N/A**
	Crossing 1 Cross Slope (%)	**0.9**		Crossing 2 Cross Slope (%)	**N/A**
Yes	Gutter Ponding	**No**	**No**	Curb Slope	**7.1**
Yes	Gutter Lip Height (in)	**0**		Road Run Slope (%)	**N/A**
Yes	Gutter Run Slope (%)	**2.6**		Road Cross Slope (%)	**N/A**
Yes	Gutter Cross Slope (%)	**0.5**			
Yes	Overall Surface Condition: **Acceptable**		**Yes**	Perp Joint Present	**Yes**
	Cross Gutter Present?	**No**		Spandrel Present?	**No**
	Replace Cross Gutter?	**N/A**		Replace Spandrel?	**N/A**