

DEPARTMENT OF TRANSPORTATION

Structure Maintenance & Investigations

Bridge Number : 55C0121

Facility Carried: BREA CANYON BLVD.

Location : 0.4 MI N/O CENTRAL AVENU

City

Inspection Date: 05/18/2012

Inspection Type

Bridge Inspection Report

Routine FC Underwater Special Other X

STRUCTURE NAME: BREA CANYON CHANNEL

CONSTRUCTION INFORMATION

Year Built : 1920 Year Widened: 1929 Length (m) : 9.1

Skew (degrees): 32 No. of Joints : No. of Hinges :

Structure Description: Continuous 2-span CIP/RC deck slab under 1.5 m of fill with an RC

pier and RC closed end backfilled strutted abutments. Foundation

type is unknown.

Span Configuration : (S) 2 @ 4.1 m (N) c/c

LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN

Operating Rating: 54.1

metric tonnes

Inventory Rating: 32.4 metric tonnes Calculation Method: LOAD FACTOR Calculation Method: LOAD FACTOR

Permit Rating : PPPPP

Posting Load : Type 3: Legal

Type 3S2:Legal

Type 3-3:Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (W) 3.4 m ea, 11 m, 0.9 m ea (E)

Total Width: 17.1 m

Net Width: 11.3 m

No. of Lanes: 2

Rail Code : 0000

Rail Description: (E) MBGR (W) None Min. Vertical Clearance: Unimpaired

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth trapezoidal with heavy bushes and trees in the channel

hed.

INSPECTION COMMENTARY

CONDITION OF STRUCTURE

There is a concrete spall (3 m \times 0.6 m \times 50 mm) at the upstream side of the pier wall in span 1 and delamination area 2 m x 0.5 m at the other face of the pier wall. Probably impacted by debris.

There is 2 mm wide cracks in both ends of pier wall.

There is 500 mm of stagnant water in span #1 (south) and there is 700 mm of dirt accumulated in span #2 (north); all elements were inspected.

Elem		Total		Qty in each Condition State					
No. Element Description	Env	Qty	Units	St. 1	St. 2	St. 3	St. 4	St.	5
<pre>39 Concrete Slab - Unprotected w/ AC Overlay</pre>	2	156	sq.m.	156	0	0	0		C
210 Reinforced Conc Pier Wall	2	17	m.	11	3	3	0		
215 Reinforced Conc Abutment	2	34	m.	34	0	0	0		C
337 Metal Railing (W6X25 Posts)	2	10	m:	10	0	0	0		(

WORK RECOMMENDATIONS

RecDate: 05/18/2012 EstCost: Repair the spall and delamination at the Action : Sub-Patch spalls StrTarget: 2 YEARS north side of the pier wall west face of Work By: LOCAL AGENCY DistTarget: the wall 3 m \times 0.6 m \times 50 mm spall and at Status : PROPOSED EA: the east face of the wall the delamination area 3 m \times 0.5 m. RecDate: 06/05/2001 EstCost: Clean the channel to improve the water Action : Remove Vegetation StrTarget: 2 YEARS flow. Remove the bushes and the trees in Work By: LOCAL AGENCY the channel bed within 30 meters of the DistTarget: Status : PROPOSED EA: bridge.

Inspected By : MT.Zaarour/A.Shenouda

Mikhael T. Zaarour (Registered Civil Engineer)



STRUCTURE INVENTORY AND APPRAISAL REPORT

	**************************************		**************
(1)	STATE NAME- CALIFORNIA 069		SUFFICIENCY RATING = 93.2
	STRUCTURE NUMBER 55C0121		STATUS
	INVENTORY ROUTE (ON/UNDER) - ON 1400M0030		HEALTH INDEX 91.1
	HIGHWAY AGENCY DISTRICT 12		PAINT CONDITION INDEX = N/A
	COUNTY CODE 059 (4) PLACE CODE 00000		******** CLASSIFICATION ******** CODE
			VDIG DDIDGE I DVGGU
	FEATURE INTERSECTED- BREA CANYON CHANNEL FACILITY CARRIED- BREA CANYON BLVD.		HICHWAY CYCEEM NOW ON MYS
	LOCATION- 0.4 MI N/O CENTRAL AVENUE		FUNCTIONAL CLASS- MINOR ARTERIAL URBAN 16
	MILEPOINT/KILOMETERPOINT 0		DEFENSE HIGHWAY- NOT STRAHNET 0
	BASE HIGHWAY NETWORK- NOT ON NET 0		PARALLEL STRUCTURE- NONE EXISTS N
(13)	LRS INVENTORY ROUTE & SUBROUTE		DIRECTION OF TRAFFIC- 2 WAY 2
(16)	LATITUDE 33 DEG 56 MIN 16.3 SEC		TEMPORARY STRUCTURE-
(17)	LONGITUDE 117 DEG 53 MIN 30 SEC		FED.LANDS HWY- NOT APPLICABLE 0
(98)	BORDER BRIDGE STATE CODE % SHARE %		DESIGNATED NATIONAL NETWORK - NOT ON NET 0
(99)	BORDER BRIDGE STRUCTURE NUMBER		TOLL- ON FREE ROAD 3
	****** STRUCTURE TYPE AND MATERIAL ******		MAINTAIN- COUNTY HIGHWAY AGENCY 02
			OWNER- COUNTY HIGHWAY AGENCY 02
(43)	STRUCTURE TYPE MAIN:MATERIAL- CONCRETE TYPE- SLAB CODE 101		HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5
(44)	STRUCTURE TYPE APPR:MATERIAL- OTHER/NA		********* CONDITION ********** CODE
	TYPE- OTHER/NA CODE 000	(58)	DECK 7
(45)	NUMBER OF SPANS IN MAIN UNIT 2	(59)	SUPERSTRUCTURE 7
(46)	NUMBER OF APPROACH SPANS 0	(60)	SUBSTRUCTURE 6
(107)	DECK STRUCTURE TYPE- CIP CONCRETE CODE 1	(61)	CHANNEL & CHANNEL PROTECTION 8
	WEARING SURFACE / PROTECTIVE SYSTEM:	(62)	CULVERTS
	TYPE OF WEARING SURFACE- GRAVEL CODE 8		****** LOAD RATING AND POSTING ****** CODE
	TYPE OF MEMBRANE- NONE CODE 0		
	TYPE OF DECK PROTECTION- NONE CODE 0		DESIGN LOAD- UNKNOWN 0
	****** AGE AND SERVICE ********		OPERATING RATING METHOD- LOAD FACTOR 1
			OPERATING RATING- 54.1
		(03)	INVENTORY RATING METHOD- LOAD FACTOR 1
	YEAR RECONSTRUCTED 1929 TYPE OF SERVICE: ON- HIGHWAY 1	V#30002-4	INVENTORY RATING- 32.4
(42)	UNDER- WATERWAY 5		BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
(28)	LANES:ON STRUCTURE 02 UNDER STRUCTURE 00	(41)	STRUCTURE OPEN, POSTED OR CLOSED- A
	AVERAGE DAILY TRAFFIC 19000		DESCRIPTION- OPEN, NO RESTRICTION
(30)	YEAR OF ADT 2009 (109) TRUCK ADT 1 %		********* APPRAISAL ********** CODE
	BYPASS, DETOUR LENGTH 2 KM	(67)	CUDITORIDAL BANKLIATION
			DECK GEOMETRY
	************ GEOMETRIC DATA ***********		UNDERCLEARANCES, VERTICAL & HORIZONTAL N
	LENGTH OF MAXIMUM SPAN 4.3 M		WATER ADEQUACY 9
	STRUCTURE LENGTH 9.1 M		APPROACH ROADWAY ALIGNMENT 8
	CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M		TRAFFIC SAFETY FEATURES 0000
	BRIDGE ROADWAY WIDTH CURB TO CURB 11.3 M		SCOUR CRITICAL BRIDGES
	DECK WIDTH OUT TO OUT 17.1 M		
	APPROACH ROADWAY WIDTH (W/SHOULDERS) 11.0 M		******* PROPOSED IMPROVEMENTS *******
	BRIDGE MEDIAN- NO MEDIAN 0	(75)	TYPE OF WORK- CODE
(34)	SKEW 32 DEG (35) STRUCTURE FLARED NO	(76)	LENGTH OF STRUCTURE IMPROVEMENT M
	INVENTORY ROUTE MIN VERT CLEAR 99.99 M	(94)	BRIDGE IMPROVEMENT COST
	INVENTORY ROUTE TOTAL HORIZ CLEAR 8.5 M	(95)	ROADWAY IMPROVEMENT COST
	MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M	(96)	TOTAL PROJECT COST
	MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M		YEAR OF IMPROVEMENT COST ESTIMATE
	MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M		FUTURE ADT 41217
(56)	MIN LAT UNDERCLEAR LT 0.0 M		YEAR OF FUTURE ADT 2029
,	************* NAVIGATION DATA **********		
(38) 1	NAVIGATION CONTROL- NOT APPLICABLE CODE N		**************************************
	PIER PROTECTION- CODE		INSPECTION DATE 05/12 (91) FREQUENCY 24 MO
	NAVIGATION VERTICAL CLEARANCE 0.0 M		CRITICAL FEATURE INSPECTION: (93) CFI DATE
	VERT-LIFT BRIDGE NAV MIN VERT CLEAR M		FRACTURE CRIT DETAIL- NO MO A)
	NAVIGATION HORIZONTAL CLEARANCE 0.0 M	В)	UNDERWATER INSP- NO MO B)
	0.0 14	C)	OTHER SPECIAL INSP- NO MO C)