



Only 3 targets with sufficient resolution. Minimum of 4 targets required for accuracy analysis.

| <input checked="" type="checkbox"/> show 'to align' entities | | | | | <input type="radio"/> | r = 20.000 | RMS < 10% |
|---|----------------|----------------|------------|-----------|--|------------|-----------|
| | X | Y | Z | Error | | | |
| A0 | 6075709.901... | 2248034.032... | 206.190219 | 0.010597 | <input checked="" type="checkbox"/> | | |
| A1 | 6075285.817... | 2248028.069... | 202.334347 | 0.0247679 | <input checked="" type="checkbox"/> | | |
| A2 | 6075284.355... | 2247830.629... | 199.901986 | 0.0230816 | <input checked="" type="checkbox"/> | | |
| | | | | | | | |
| <input checked="" type="checkbox"/> show 'reference' entities | | | | | <input type="radio"/> | | |
| | X | Y | Z | Error | | | |
| R0 | 6075709.900... | 2248034.151... | 206.213000 | 0.010597 | <input checked="" type="checkbox"/> | | |
| R1 | 6075285.783... | 2248028.030... | 202.365000 | 0.0247679 | <input checked="" type="checkbox"/> | | |
| R2 | 6075284.340... | 2247830.560... | 199.901000 | 0.0230816 | <input checked="" type="checkbox"/> | | |
| | | | | | | | |
| <input checked="" type="checkbox"/> adjust scale | | | | | Rotation <input type="button" value="XYZ"/> <input checked="" type="checkbox"/> Tx <input checked="" type="checkbox"/> Ty <input checked="" type="checkbox"/> Tz | | |
| <input type="checkbox"/> auto update zoom | | | | | <input type="button" value="align"/> <input type="button" value="reset"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> | | |

Error in meters

