

Access Compliance Report - Public Rights-of-Way (Corridor: Sidewalk & Intersection Items)

Corridor ID: ANTIGUA_ST_003





ADA Survey Summary

Item	Description	Qua	Quantity	
1	Vertical Displacement <= 1"	5	EA	
2	Vertical Displacement > 1"	2	EA	
3	Uneven Vertical Displacement	0	EA	
2 3 4 5 6 7	Horizontal Opening > 0.5"	0	EA	
5	Poor Surface Condition	0	SY	
6	Utility Obstruction	0	EA	
7	Power Pole Obstruction	0	EA	
8	Traffic Signal Obstruction	0	EA	
9	Sign Obstruction	0	EA	
10	Low Vegetative Obstruction	0	EA	
11	Overhead Vegetative Obstruction	0	EA	
12	Other Obstruction*	0	EA	
13	Miscellaneous Obstruction	0	EA	
14	Temp/Private Obstruction	0	EA	
<u>15</u>	Commercial Driveway	0	<u>LF</u>	
<u>16</u>	Residential Driveway	54	<u>LF</u>	
<u>17</u>	Total Sidewalk Length Assessed	495	<u>LF</u>	
18	Average Sidewalk Width	54	IN	
19	Curb Ramps In Corridor	3	EA	
20	Island Curb Cuts In Corridor	0	EA	
21	Signal Push Buttons In Corridor	0	EA	
22	Accessible Parking Spaces In Corridor	0	EA	
23	Missing Sidewalk/Gaps in Connectivity	0	<u>LF</u>	
24	Buried/Narrow Sidewalk	0	<u>LF</u>	
25	Sidewalk Not Surveyed	0	LF	
26	No Sidewalk Observed	0	<u>LF</u>	
27	Corridor Severity Score	4.05		

 $\underline{http://www.google.com/maps/@?api=1\&map_action=pano\&viewpoint=33.81391586,-117.96181245}$

Inventory Symbology

Running Slope (Aligned, Not Costed)

> 8.4 - 10.0% 10.1 - 12.5% 12.5%+

5.1 - 8.3%

Collection in Adjacent Corridors

Curb Ramps

Island Curb Cuts Signal Push Buttons

Sidewalk Collection

ltem	Description	Quantity	Unit	Unit Price	Item Cost
1	Vertical Displacement <= 1"	0	EΑ	\$150.00	\$ 0.00
2	Vertical Displacement > 1"	0	EΑ	\$2125.00	\$ 0.00
3	Uneven Vertical Displacement	0	EΑ	\$2125.00	\$ 0.00
4	Horizontal Opening > 0.5"	0	EΑ	\$1062.00	\$ 0.00
5	Poor Surface Condition	0	SY	\$255.50	\$ 0.00
6	Utility Obstruction	0	EΑ	\$5000.00	\$ 0.00
7	Power Pole Obstruction	0	EΑ	\$20000.00	\$ 0.00
8	Traffic Signal Obstruction	0	EΑ	\$5000.00	\$ 0.00
9	Sign Obstruction	0	EΑ	\$2000.00	\$ 0.00
10	Low Vegetative Obstruction	0	EΑ	\$200.00	\$ 0.00
<u>11</u>	Overhead Vegetative Obstruction	0	EΑ	\$400.00	\$ 0.00
12	Other Obstruction*	0	EΑ	\$2000.00	\$ 0.00
13	Miscellaneous Obstruction	0	ΕA	\$2000.00	\$ 0.00
14	Commercial Driveway	0	LF	\$118.00	\$ 0.00
15	Residential Driveway	54	LF	\$118.00	\$ 6392.00
16	Running Slope Violation	0	SY	\$255.50	\$ 0.00
<u>17</u>	Cross Slope Violation	210	SY	\$255.50	\$ 53678.00
18	Running and Cross Slope violations	1	SY	\$255.50	\$ 448.00
19	Non-Compliant Curb Ramps and Total Cost*	3	EΑ	VARIES	\$ 15700.00
20	Non-Compliant Island Curb Cuts and Total Cost*	0	EΑ	VARIES	\$ 0.00
<u>21</u>	Non-Compliant Signal Push Buttons Cuts and Total	al Cost* 0	EΑ	VARIES	\$ 0.00
22	Non-Compliant Accessible Parking Spaces and To	otal Cost* 0	EΑ	VARIES	\$ 0.00
23	Missing Sidewalk/Gap in Connectivity	0	SY	\$150.00	\$ 0.00
24	Buried/Narrow Sidewalk	0	SY	\$255.50	\$ 0.00

Compliance Symbology

Compliant Curb Ramp

Non-Compliant Curb Ramp

Compliant Island Curb Cut

Non-Compliant Island Curb Cut

Compliant Signal

Non-Compliant Signal

Cross Slope

2.01 - 3.0% 3.01 - 4.0% 4.01 - 5.0% 5.01%+

Running Slope

(Deviated, Costed)

5.1 - 8.3%8.4 - 10.0% 10.1 - 12.5%

12.5%+

Google Street View Link

*Note: Some items combined for display. See Unit Cost Table for specific unit costs for each type of obstruction, curb ramp, island curb cut. Missing sidewalk/gaps in

\$76,218.00

Total: \$