

## Access Compliance Report - Public Rights-of-Way (Corridor: Sidewalk & Intersection Items)

Corridor ID: E\_AVENIDA\_PALMAR\_001





ADA Survey Summa	ry
------------------	----

Item	Description	Qua	Quantity	
1	Vertical Displacement <= 1"	23	EA	
2	Vertical Displacement > 1"	0	EA	
3	Uneven Vertical Displacement	0	EA	
2 3 4	Horizontal Opening > 0.5"	0	EA	
	Poor Surface Condition	0	SY	
<u>5</u>	Utility Obstruction	0	EA	
7	Power Pole Obstruction	0	EA	
8	Traffic Signal Obstruction	0	EA	
9	Sign Obstruction	0	EA	
10	Low Vegetative Obstruction	0	EA	
11	Overhead Vegetative Obstruction	0	EA	
12	Other Obstruction*	0	EA	
13	Miscellaneous Obstruction	0	EA	
14	Temp/Private Obstruction	0	EA	
15	Commercial Driveway	0	LF	
16	Residential Driveway	205	LF	
<u>17</u>	Total Sidewalk Length Assessed	1230	<u>LF</u>	
18	Average Sidewalk Width	48	IN	
19	Curb Ramps In Corridor	1	EA	
20	Island Curb Cuts In Corridor	0	EA	
21	Signal Push Buttons In Corridor	0	<u>EA</u>	
22	Accessible Parking Spaces In Corridor	0	EA	
23	Missing Sidewalk/Gaps in Connectivity	0	LF	
24	Buried/Narrow Sidewalk	0	LF	
25	Sidewalk Not Surveyed	0	LF	
26	No Sidewalk Observed	0	LF	
27	Corridor Severity Score	4.11		

## Inventory Symbology Running Slope

(Aligned, Not Costed)
5.1 – 8.3%

8.4 – 10.0% 10.1 – 12.5% 12.5%+

Collection in Adjacent Corridors

Curb Ramps
Sland Curb Cuts

Signal Push Buttons
Sidewalk Collection

## ADA Compliance Cost Estimate \*\*

Item	Description	Quantity I	Jnit	<b>Unit Price</b>	Item Cost
1	Vertical Displacement <= 1"	7	EΑ	\$150.00	\$ 1050.00
2	Vertical Displacement > 1"	0	EΑ	\$2125.00	\$ 0.00
3	Uneven Vertical Displacement	0	EΑ	\$2125.00	\$ 0.00
4	Horizontal Opening > 0.5"	0	EΑ	\$1062.00	\$ 0.00
5	Poor Surface Condition	0	SY	\$255.50	\$ 0.00
6	Utility Obstruction	0	EΑ	\$5000.00	\$ 0.00
7	Power Pole Obstruction	0	EΑ	\$20000.00	\$ 0.00
8	Traffic Signal Obstruction	0	EΑ	\$5000.00	\$ 0.00
9	Sign Obstruction	0	EΑ	\$2000.00	\$ 0.00
10	Low Vegetative Obstruction	0	EΑ	\$200.00	\$ 0.00
<u>11</u>	Overhead Vegetative Obstruction	0	EΑ	\$400.00	\$ 0.00
12	Other Obstruction*	0	EΑ	\$2000.00	\$ 0.00
13	Miscellaneous Obstruction	0	EΑ	\$2000.00	\$ 0.00
14	Commercial Driveway	0	LF	\$118.00	\$ 0.00
<u>15</u>	Residential Driveway	195	LF	\$118.00	\$ 23109.00
<u>16</u>	Running Slope Violation	0	SY	\$255.50	\$ 0.00
<u>17</u>	Cross Slope Violation	334	SY	\$255.50	\$ 85587.00
18	Running and Cross Slope violations	0	SY	\$255.50	\$ 0.00
19	Non-Compliant Curb Ramps and Total Cost*	1	EΑ	VARIES	\$ 4000.00
20	Non-Compliant Island Curb Cuts and Total Cost	* 0	EΑ	VARIES	\$ 0.00
21	Non-Compliant Signal Push Buttons Cuts and To	otal Cost* 0	EΑ	VARIES	\$ 0.00
22	Non-Compliant Accessible Parking Spaces and	Total Cost* 0	EΑ	VARIES	\$ 0.00
23	Missing Sidewalk/Gap in Connectivity	0	SY	\$150.00	\$ 0.00
24	Buried/Narrow Sidewalk	0	SY	\$255.50	\$ 0.00

## **Compliance Symbology**

Compliant Curb Ramp

Non-Compliant Curb Ramp

Compliant Island Curb Cut

Non-Compliant Island Curb Cut

Compliant Signal

Non-Compliant Signal

Cross Slope

2.01 - 3.0% 3.01 - 4.0%

4.01 - 5.0%

5.01%+

Running Slope

(Deviated, Costed)

5.1 – 8.3% 8.4 – 10.0%

---

10.1 – 12.5%

12.5%+

Google Street View Link

Total: \$ \$113,747.00

<sup>\*</sup>Note: Some items combined for display. See Unit Cost Table for specific unit costs for each type of obstruction, curb ramp, island curb cut. Missing sidewalk/gaps in connectivity reported together in compliance report and are separate in the GIS layers."

\*\*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a