

Parcel ID Number

Google Street View Link

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Main Street: DORRANCE DR Cross Street:DORRANCE_DR Location: SE ADA ID: CCRK211102130308 Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Pass **Overall Compliance: No Severity Score:** 15

Codes/Mitigation Info/Possible Solution



Install Detectable Warning System.

Surveyor Notes:

Possible Solutions:

N/A

OC Std/PROW:

R305, STD 1115

Total Cost:

1200

741-141-50 Street 1 Name DORRANCE_DR Stop Condition-Street 1 N/A Street 2 Name DORRANCE_DR Stop Condition-Street 2 N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.55482937,-117.64495873

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Com	pliance Description	<u>Data</u>
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A



Field Measurements/Component Compliance									
Compliance Description			Data	Compliance Description		Data			
	Yes	Refuge 1 Length (In)	113	Yes	Guttter 1 Ponding	No			
	Yes	Refuge 1 Width (In)	96	Yes	Gutter 1 Lip Ht (In)	0			
	Yes	Refuge 1 Slope (%)	0.9	Yes	Gutter 1 Slope (%)	0.7			
	Yes	Refuge 1 Cross Slope (%)	2.3	Yes	Gutter 1 Cross Slope (%)	0.5			
	N/A	Painted Cross Walk 1	Yes	No	DWS 1 Provided	No			
		Cross Walk 1 Direction	N	N/A	DWS 1 Contrast	N/A			
		Cross Walk 1 Width (In)	144	N/A	DWS 1 Length (In)	N/A			
	Yes	Refuge Inside Cross Walk 1	Yes	N/A	DWS 1 Full Width	N/A			
		Road 1 Slope (%)	1.8	N/A	DWS 1 Offset (In)	N/A			
		Road 1 Cross Slope (%)	1.6			N/A			
	Yes	Refuge 2 Length (In)	108	Yes	Guttter 2 Ponding	No			
	Yes	Refuge 2 Width (In)	96	Yes	Gutter 2 Lip Ht (In)	0			
	Yes	Refuge 2 Slope (%)	2.1	Yes	Gutter 2 Slope (%)	1.6			
	Yes	Refuge 2 Cross Slope (%)	1.1	Yes	Gutter 2 Cross Slope (%)	0.7			
)	N/A	Painted Cross Walk 2	Yes	No	DWS 2 Provided	No			
		Cross Walk 2 Direction	S	N/A	DWS 2 Contrast	N/A			
2		Cross Walk 2 Width (In)	144	N/A	DWS 2 Length (In)	N/A			
١.	Yes	Refuge Inside Cross Walk 2	Yes	N/A	DWS 2 Full Width	N/A			
2		Road 2 Slope (%)	3.7	N/A	DWS 2 Offset (In)	N/A			
١		Road 2 Cross Slope (%)	0.6						
	Yes	Overall Surface Condition: Acce	ptable						
				•					