

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Main Street: O NEILL DR Cross Street:O_NEILL_DR Location: Ν ADA ID: CCRK211103153226 Curb Cut Type: MedianRefuge2 **Initial Pass/Fail: Pass Overall Compliance: No Severity Score:** 15

Codes/Mitigation Info/Possible Solution



Install Detectable Warning System.

Surveyor Notes:

N/A

OC Std/PROW:

R305, STD 1115

Total Cost:

1200

Street 1 Name O_NEILL_DR Stop Condition-Street 1 N/A Street 2 Name O_NEILL_DR


Stop Condition-Street 2 N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.54787159,-117.64528339

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data	Compliance Description	<u>Data</u>
Yes Obstructions Present?	No	N/A Utilities Present?	No
Obstruction Types	N/A	Utility Types	
Obstruction Dimensions	N/A		N/A

741-272-19



Parcel ID Number

Google Street View Link





Field Measurements/Component Compliance									
1	Compliance Description		Data	Compliance Description		Data			
	Yes	Refuge 1 Length (In)	118	Yes	Guttter 1 Ponding	No			
	Yes	Refuge 1 Width (In)	96	Yes	Gutter 1 Lip Ht (In)	0			
	Yes	Refuge 1 Slope (%)	0.3	Yes	Gutter 1 Slope (%)	0.7			
	Yes	Refuge 1 Cross Slope (%)	0.6	Yes	Gutter 1 Cross Slope (%)	0.2			
	N/A	Painted Cross Walk 1	Yes	No	DWS 1 Provided	No			
		Cross Walk 1 Direction	E	N/A	DWS 1 Contrast	N/A			
		Cross Walk 1 Width (In)	144	N/A	DWS 1 Length (In)	N/A			
	Yes	Refuge Inside Cross Walk 1	Yes	N/A	DWS 1 Full Width	N/A			
		Road 1 Slope (%)	3.9	N/A	DWS 1 Offset (In)	N/A			
		Road 1 Cross Slope (%)	0.1			N/A			
	Yes	Refuge 2 Length (In)	122	Yes	Guttter 2 Ponding	No			
	Yes	Refuge 2 Width (In)	96	Yes	Gutter 2 Lip Ht (In)	0			
	Yes	Refuge 2 Slope (%)	0.3	Yes	Gutter 2 Slope (%)	4			
	Yes	Refuge 2 Cross Slope (%)	0.9	Yes	Gutter 2 Cross Slope (%)	2.1			
,	N/A	Painted Cross Walk 2	Yes	No	DWS 2 Provided	No			
		Cross Walk 2 Direction	w	N/A	DWS 2 Contrast	N/A			
2		Cross Walk 2 Width (In)	144	N/A	DWS 2 Length (In)	N/A			
١	Yes	Refuge Inside Cross Walk 2	Yes	N/A	DWS 2 Full Width	N/A			
2		Road 2 Slope (%)	2.2	N/A	DWS 2 Offset (In)	N/A			
١		Road 2 Cross Slope (%)	1.2						
	Yes	Overall Surface Condition: Acce	ptable						