



Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Main Street: SOL_ST Cross Street: SOL_ST Location: W

ADA ID: CCRK211104124436 Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 15

Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance



Possible Solutions:
Install Detectable Warning System. Remove & Replace Gutter.

Surveyor Notes:
N/A

OC Std/PROW:
R305, R304.5.3, STD 1115

Total Cost: \$ **1452**

Parcel ID Number **741-274-29**

Google Street View Link
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.54132749,-117.6444865

Street 1 Name **SOL_ST**
Stop Condition-Street 1 **N/A**
Street 2 Name **SOL_ST**
Stop Condition-Street 2 **N/A**

Compliance	Description	Data	Compliance	Description	Data
Yes	Refuge 1 Length (In)	60	Yes	Guttter 1 Ponding	No
Yes	Refuge 1 Width (In)	96	Yes	Gutter 1 Lip Ht (In)	0
Yes	Refuge 1 Slope (%)	3.1	Yes	Gutter 1 Slope (%)	2.1
Yes	Refuge 1 Cross Slope (%)	1	Yes	Gutter 1 Cross Slope (%)	0.6
N/A	Painted Cross Walk 1	Yes	No	DWS 1 Provided	No
	Cross Walk 1 Direction	S	N/A	DWS 1 Contrast	N/A
	Cross Walk 1 Width (In)	144	N/A	DWS 1 Length (In)	N/A
Yes	Refuge Inside Cross Walk 1	Yes	N/A	DWS 1 Full Width	N/A
	Road 1 Slope (%)	1.5	N/A	DWS 1 Offset (In)	N/A
	Road 1 Cross Slope (%)	1.1			N/A
Yes	Refuge 2 Length (In)	60	Yes	Guttter 2 Ponding	No
Yes	Refuge 2 Width (In)	96	Yes	Gutter 2 Lip Ht (In)	0
Yes	Refuge 2 Slope (%)	4.1	Yes	Gutter 2 Slope (%)	1.4
Yes	Refuge 2 Cross Slope (%)	1.6	No	Gutter 2 Cross Slope (%)	3.2
N/A	Painted Cross Walk 2	Yes	No	DWS 2 Provided	No
	Cross Walk 2 Direction	N	N/A	DWS 2 Contrast	N/A
	Cross Walk 2 Width (In)	144	N/A	DWS 2 Length (In)	N/A
Yes	Refuge Inside Cross Walk 2	Yes	N/A	DWS 2 Full Width	N/A
	Road 2 Slope (%)	2.3	N/A	DWS 2 Offset (In)	N/A
	Road 2 Cross Slope (%)	0.9			
Yes	Overall Surface Condition: Acceptable				

Obstruction and Utility Measurement/Component Compliance					
Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

