

## **Access Compliance Report Public Rights-of-Way** (Island Curb Cuts)



Main Street: WINDMILL\_AVE **Cross Street:WINDMILL\_AVE** Location: ADA ID: CCRK211109120207 **Overall Compliance: No** Curb Cut Type: MedianRefuge2 **Initial Pass/Fail: Pass Severity Score:** 15

**Codes/Mitigation Info/Possible Solution** 



Possible Solutions: Install Detectable Warning System.

Surveyor Notes:

N/A

OC Std/PROW:

R305, STD 1115

Parcel ID Number 759-451-29

Google Street View Link

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.

	Total Cost: \$ 1200	N/		
9	Street 1 Name WINDMILL_AVE			
	Stop Condition-Street 1 N/A	Ye		
	Street 2 Name WINDMILL_AVE			
	Stop Condition-Street 2 N/A			
.55	5583614,-117.63550624			

Obstruction and Utility	/ Measurement/Compo	nent Compliance
-------------------------	---------------------	-----------------

Compliance Description	Data Compliance Description	Data
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A



Field Measurements/Component Compliance									
1	Com	pliance Description	Data	Com	pliance Description	Data			
	Yes	Refuge 1 Length (In)	108	Yes	Guttter 1 Ponding	No			
	Yes	Refuge 1 Width (In)	96	Yes	Gutter 1 Lip Ht (In)	0			
	Yes	Refuge 1 Slope (%)	4.9	Yes	Gutter 1 Slope (%)	2			
	Yes	Refuge 1 Cross Slope (%)	2.1	Yes	Gutter 1 Cross Slope (%)	1.2			
	N/A	Painted Cross Walk 1	Yes	No	DWS 1 Provided	No			
		Cross Walk 1 Direction	s	N/A	DWS 1 Contrast	N/A			
		Cross Walk 1 Width (In)	144	N/A	DWS 1 Length (In)	N/A			
	Yes	Refuge Inside Cross Walk 1	Yes	N/A	DWS 1 Full Width	N/A			
		Road 1 Slope (%)	3.9	N/A	DWS 1 Offset (In)	N/A			
		Road 1 Cross Slope (%)	0.4			N/A			
	Yes	Refuge 2 Length (In)	108	Yes	Guttter 2 Ponding	No			
	Yes	Refuge 2 Width (In)	96	Yes	Gutter 2 Lip Ht (In)	0			
	Yes	Refuge 2 Slope (%)	0.7	Yes	Gutter 2 Slope (%)	0.3			
	Yes	Refuge 2 Cross Slope (%)	2.1	Yes	Gutter 2 Cross Slope (%)	0.8			
,	N/A	Painted Cross Walk 2	Yes	No	DWS 2 Provided	No			
		Cross Walk 2 Direction	N	N/A	DWS 2 Contrast	N/A			
:		Cross Walk 2 Width (In)	144	N/A	DWS 2 Length (In)	N/A			
۱	Yes	Refuge Inside Cross Walk 2	Yes	N/A	DWS 2 Full Width	N/A			
:		Road 2 Slope (%)	2.2	N/A	DWS 2 Offset (In)	N/A			
۱		Road 2 Cross Slope (%)	0.6						
	Yes	Overall Surface Condition: Acce	ptable						
				J					