



# Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



|                                         |                             |                          |                                         |                 |    |
|-----------------------------------------|-----------------------------|--------------------------|-----------------------------------------|-----------------|----|
| Main Street:N_DAISSY_ST                 |                             | Cross Street:SIENNA_PKWY |                                         | Location:       | E  |
| ADA ID: CCRK211110125423                | Curb Cut Type:MedianRefuge2 | Initial Pass/Fail: Pass  | Overall Compliance: No                  | Severity Score: | 15 |
| Codes/Mitigation Info/Possible Solution |                             |                          | Field Measurements/Component Compliance |                 |    |



Possible Solutions:

Install Detectable Warning System.

Surveyor Notes:

N/A

OC Std/PROW:

R305, STD 1115

Total Cost:

\$ 1200

Parcel ID Number

741-211-02

Street 1 Name

N\_DAISSY\_ST

Stop Condition-Street 1

N/A

Street 2 Name

SIENNA\_PKWY

Stop Condition-Street 2

N/A

Google Street View Link

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.5520561,-117.63815468](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.5520561,-117.63815468)

| Compliance | Description                           | Data | Compliance | Description              | Data |
|------------|---------------------------------------|------|------------|--------------------------|------|
| Yes        | Refuge 1 Length (In)                  | 84   | Yes        | Guttter 1 Ponding        | No   |
| Yes        | Refuge 1 Width (In)                   | 96   | Yes        | Gutter 1 Lip Ht (In)     | 0    |
| Yes        | Refuge 1 Slope (%)                    | 3.2  | Yes        | Gutter 1 Slope (%)       | 1.6  |
| Yes        | Refuge 1 Cross Slope (%)              | 0.8  | Yes        | Gutter 1 Cross Slope (%) | 0.2  |
| N/A        | Painted Cross Walk 1                  | Yes  | No         | DWS 1 Provided           | No   |
|            | Cross Walk 1 Direction                | N    | N/A        | DWS 1 Contrast           | N/A  |
|            | Cross Walk 1 Width (In)               | 144  | N/A        | DWS 1 Length (In)        | N/A  |
| Yes        | Refuge Inside Cross Walk 1            | Yes  | N/A        | DWS 1 Full Width         | N/A  |
|            | Road 1 Slope (%)                      | 1.1  | N/A        | DWS 1 Offset (In)        | N/A  |
|            | Road 1 Cross Slope (%)                | 3.9  |            |                          | N/A  |
| Yes        | Refuge 2 Length (In)                  | 79   | Yes        | Guttter 2 Ponding        | No   |
| Yes        | Refuge 2 Width (In)                   | 96   | Yes        | Gutter 2 Lip Ht (In)     | 0    |
| Yes        | Refuge 2 Slope (%)                    | 4.2  | Yes        | Gutter 2 Slope (%)       | 2.6  |
| Yes        | Refuge 2 Cross Slope (%)              | 0.3  | Yes        | Gutter 2 Cross Slope (%) | 1.3  |
| N/A        | Painted Cross Walk 2                  | Yes  | No         | DWS 2 Provided           | No   |
|            | Cross Walk 2 Direction                | S    | N/A        | DWS 2 Contrast           | N/A  |
|            | Cross Walk 2 Width (In)               | 144  | N/A        | DWS 2 Length (In)        | N/A  |
| Yes        | Refuge Inside Cross Walk 2            | Yes  | N/A        | DWS 2 Full Width         | N/A  |
|            | Road 2 Slope (%)                      | 0.6  | N/A        | DWS 2 Offset (In)        | N/A  |
|            | Road 2 Cross Slope (%)                | 2    |            |                          |      |
| Yes        | Overall Surface Condition: Acceptable |      |            |                          |      |

## Obstruction and Utility Measurement/Component Compliance

| Compliance | Description            | Data | Compliance | Description        | Data |
|------------|------------------------|------|------------|--------------------|------|
| Yes        | Obstructions Present?  | No   | N/A        | Utilities Present? | No   |
|            | Obstruction Types      | N/A  |            | Utility Types      |      |
|            | Obstruction Dimensions | N/A  |            |                    | N/A  |

