



# Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



|                                         |                              |                          |                                         |                 |    |
|-----------------------------------------|------------------------------|--------------------------|-----------------------------------------|-----------------|----|
| Main Street: ESENCIA_DR                 |                              | Cross Street: ESENCIA_DR |                                         | Location:       | S  |
| ADA ID: CCRK211129124435                | Curb Cut Type: MedianRefuge2 | Initial Pass/Fail: Pass  | Overall Compliance: No                  | Severity Score: | 10 |
| Codes/Mitigation Info/Possible Solution |                              |                          | Field Measurements/Component Compliance |                 |    |



Possible Solutions:

Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.5.4, R304.5.3, STD 1115

Total Cost:

\$ 252

Parcel ID Number

755-351-06

Street 1 Name

ESENCIA\_DR

Stop Condition-Street 1

N/A

Street 2 Name

ESENCIA\_DR

Stop Condition-Street 2

N/A

Google Street View Link

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.53354044,-117.6009509](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.53354044,-117.6009509)

| Compliance | Description                           | Data | Compliance | Description              | Data |
|------------|---------------------------------------|------|------------|--------------------------|------|
| Yes        | Refuge 1 Length (In)                  | 54   | Yes        | Guttter 1 Ponding        | No   |
| Yes        | Refuge 1 Width (In)                   | 96   | Yes        | Gutter 1 Lip Ht (In)     | 0    |
| Yes        | Refuge 1 Slope (%)                    | 2.5  | No         | Gutter 1 Slope (%)       | 6.5  |
| Yes        | Refuge 1 Cross Slope (%)              | 3.2  | No         | Gutter 1 Cross Slope (%) | 3.6  |
| N/A        | Painted Cross Walk 1                  | Yes  | Yes        | DWS 1 Provided           | Yes  |
|            | Cross Walk 1 Direction                | W    | Yes        | DWS 1 Contrast           | Yes  |
|            | Cross Walk 1 Width (In)               | 145  | Yes        | DWS 1 Length (In)        | 36   |
| Yes        | Refuge Inside Cross Walk 1            | Yes  | Yes        | DWS 1 Full Width         | Yes  |
|            | Road 1 Slope (%)                      | 0.2  | Yes        | DWS 1 Offset (In)        | 0    |
|            | Road 1 Cross Slope (%)                | 3.3  |            |                          | N/A  |
| Yes        | Refuge 2 Length (In)                  | 54   | Yes        | Guttter 2 Ponding        | No   |
| Yes        | Refuge 2 Width (In)                   | 96   | Yes        | Gutter 2 Lip Ht (In)     | 0    |
| Yes        | Refuge 2 Slope (%)                    | 3.4  | Yes        | Gutter 2 Slope (%)       | 4.2  |
| Yes        | Refuge 2 Cross Slope (%)              | 1.6  | Yes        | Gutter 2 Cross Slope (%) | 1.1  |
| N/A        | Painted Cross Walk 2                  | Yes  | Yes        | DWS 2 Provided           | Yes  |
|            | Cross Walk 2 Direction                | E    | Yes        | DWS 2 Contrast           | Yes  |
|            | Cross Walk 2 Width (In)               | 144  | Yes        | DWS 2 Length (In)        | 36   |
| Yes        | Refuge Inside Cross Walk 2            | Yes  | Yes        | DWS 2 Full Width         | Yes  |
|            | Road 2 Slope (%)                      | 2.4  | Yes        | DWS 2 Offset (In)        | 0    |
|            | Road 2 Cross Slope (%)                | 0.8  |            |                          |      |
| Yes        | Overall Surface Condition: Acceptable |      |            |                          |      |

## Obstruction and Utility Measurement/Component Compliance

| Compliance | Description            | Data | Compliance | Description        | Data |
|------------|------------------------|------|------------|--------------------|------|
| Yes        | Obstructions Present?  | No   | N/A        | Utilities Present? | No   |
|            | Obstruction Types      | N/A  |            | Utility Types      |      |
|            | Obstruction Dimensions | N/A  |            |                    | N/A  |

