




Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Main Street: ADAMS_ST		Cross Street: BOLSA_AVE		Location:	S
ADA ID: CCRK220202155122	Curb Cut Type: NoAccess	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score:	0
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		



Possible Solutions:

Provide Island Refuge.

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

\$ 5000

Parcel ID Number

107-151-56

Street 1 Name

ADAMS_ST

Stop Condition-Street 1

N/A

Street 2 Name

BOLSA_AVE

Stop Condition-Street 2

N/A

Google Street View Link

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.74451095,-117.9884679

Compliance	Description	Data	Compliance	Description	Data
------------	-------------	------	------------	-------------	------

