



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: GILBERT_ST Cross Street: BANTA_AVE Location: NW

ADA ID: RPAT210916093703 Ramp Type: Type 4 - Parallel Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 5

Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance



Possible Solutions:
Remove & Replace Curb Slope. Remove & Replace Gutter. Utility Present.

Surveyor Notes:
N/A

OC Std/PROW:
R304.2.2, R304.5.4, STD 1115

Total Cost: \$ 504

Parcel ID Number **127-573-43**
Ramp Island Or Median **None**
Ramp Orientation **NonDiag**
Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.80558496,-117.96768511

Street 1 Name **GILBERT_ST**
Stop Condition-Street 1 **YieldSign**
Street 2 Name **BANTA_AVE**
Stop Condition-Street 2 **N/A**

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	Yes
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A		Pushbutton Post	



Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	96	N/A	Ramp Length RT (in)	97
Yes	Ramp Width LT (in)	65	Yes	Ramp Width RT (in)	52
Yes	Ramp Run Slope LT (%)	7.8	Yes	Ramp Run Slope RT (%)	7.9
Yes	Ramp Cross Slope LT (%)	0.1	Yes	Ramp Cross Slope RT (%)	0.5
N/A	Landing Present	Yes	Yes	DWS Provided	Yes
N/A	Landing Length (in)	64	Yes	DWS Contrast	Yes
Yes	Landing Width (in)	60	Yes	DWS Length (in)	36
Yes	Landing Run Slope (%)	0.6	Yes	DWS Full Width	Yes
Yes	Landing Cross Slope (%)	1.2		DWS Offset Type	Single
N/A	Landing Movement Obstructed?	No	Yes	DWS Offset Left (in)	0
	Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A
N/A	Landing Shared	No			
N/A	Clear Space	N/A			
N/A	Clear Space To Crosswalk (in)	N/A			
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	N/A
	Crossing 1 Direction	E		Crossing 2 Direction	N/A
	Marked Crosswalk 1 Width (in)	119		Marked Crosswalk 2 Width (in)	N/A
Yes	Ramp Inside Crosswalk 1	Yes	N/A	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	2.8		Crossing 2 Slope (%)	N/A
	Crossing 1 Cross Slope (%)	0.2		Crossing 2 Cross Slope (%)	N/A
Yes	Gutter Ponding	No	No	Curb Slope	10.3
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
No	Gutter Run Slope (%)	9.2		Road Cross Slope (%)	N/A
Yes	Gutter Cross Slope (%)	0	Yes	Perpendicular Joint Present	Yes
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A