

Parcel ID Number

Ramp Orientation

Ramp Island Or Median

Google Street View Link:

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Main Street: CANTON AVE Cross Street: ENDRY ST Location: NW ADA ID: RPAT210916124218 Ramp Type: No Ramp Initial Pass/Fail: N/A **Overall Compliance: No Severity Score:** 100

> **Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance**

> > 3080

N/A

Compliance Description

CANTON_AVE

Possible Solutions: **Provide Curb Ramp**

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

127-583-02 Street 1 Name **CANTON AVE** Stop Condition-Street 1 N/A

ENDRY_ST Street 2 Name

Stop Condition-Street 2

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.80476909,-117.96704615

Data Compliance

Description

