



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



**Main Street: JEAN\_ST** **Cross Street: DECKER\_AVE** **Location: SW**

**ADA ID: RPAT210916134305** **Ramp Type: Type 4 - Parallel** **Initial Pass/Fail: Pass** **Overall Compliance: No** **Severity Score: 0**

**Codes/Mitigation Info/Possible Solution** **Field Measurements/Component Compliance**



**Possible Solutions:**  
Remove & Replace Landing.

**Surveyor Notes:**  
N/A

**OC Std/PROW:**  
R304.2.2-Perp, R304.3.2-Para, STD 1115

**Total Cost:** \$ 531

**Parcel ID Number:** 127-583-35  
**Ramp Island Or Median:** None  
**Ramp Orientation:** Diag  
**Google Street View Link:**  
[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.80390064,-117.96380184](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.80390064,-117.96380184)

**Street 1 Name:** JEAN\_ST  
**Stop Condition-Street 1:** NoControl  
**Street 2 Name:** DECKER\_AVE  
**Stop Condition-Street 2:** NoControl

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	79	N/A	Ramp Length RT (in)	76
Yes	Ramp Width LT (in)	52	Yes	Ramp Width RT (in)	59
Yes	Ramp Run Slope LT (%)	6.4	Yes	Ramp Run Slope RT (%)	4.8
Yes	Ramp Cross Slope LT (%)	0.5	Yes	Ramp Cross Slope RT (%)	0.1
N/A	Landing Present	Yes	Yes	DWS Provided	Yes
N/A	Landing Length (in)	60	Yes	DWS Contrast	Yes
Yes	Landing Width (in)	48	Yes	DWS Length (in)	36
No	Landing Run Slope (%)	2.8	Yes	DWS Full Width	Yes
Yes	Landing Cross Slope (%)	0.2		DWS Offset Type	Single
N/A	Landing Movement Obstructed?	No	Yes	DWS Offset Left (in)	0
	Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A
N/A	Landing Shared	No			
N/A	Clear Space	Yes			
N/A	Clear Space To Crosswalk (in)	48			
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	E		Crossing 2 Direction	N
N/A	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	2.3		Crossing 2 Slope (%)	5.6
	Crossing 1 Cross Slope (%)	0.7		Crossing 2 Cross Slope (%)	0.7
Yes	Gutter Ponding	No	Yes	Curb Slope	5
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	2.2
Yes	Gutter Run Slope (%)	1.3		Road Cross Slope (%)	0.2
Yes	Gutter Cross Slope (%)	0.4	Yes	Perpendicular Joint Present	Yes
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	Yes		Spandrel Present?	Yes
	Replace Cross Gutter?	No		Replace Spandrel?	No

**Obstruction and Utility Measurement/Component Compliance**

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

