Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Main Street: CRESTWOOD_LN | **Cross Street:** CRESTWOOD_LN | **Location:** NW

ADA ID: RPAT210916151320 | **Ramp Type:** No Ramp | **Initial Pass/Fail:** N/A | **Overall Compliance:** No | **Severity Score:** 100

Codes/Mitigation Info/Possible Solution

Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost: **$ 3080**

Parcel ID Number	**127-591-23**	Street 1 Name	**CRESTWOOD_LN**
Ramp Island Or Median	**N/A**	Stop Condition-Street 1	**N/A**
Ramp Orientation	**N/A**	Street 2 Name	**CRESTWOOD_LN**
Google Street View Link:		Stop Condition-Street 2	**N/A**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.80636417,-117.96382118





Field Measurements/Component Compliance

Compliance	Description	Data	Compliance	Description	Data