Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Main Street: PALM_DR | **Cross Street: CEDARLAWN_DR** | **Location: SE**

ADA ID: RPAT210917103056 | **Ramp Type: No Ramp** | **Initial Pass/Fail: N/A** | **Overall Compliance: No** | **Severity Score: 100**

Codes/Mitigation Info/Possible Solution

Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost: **$ 3080**

Parcel ID Number	**340-021-57**	Street 1 Name	**PALM_DR**
Ramp Island Or Median	**N/A**	Stop Condition-Street 1	**N/A**
Ramp Orientation	**N/A**	Street 2 Name	**CEDARLAWN_DR**
Google Street View Link:		Stop Condition-Street 2	**N/A**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.88379283,-117.84890505

Field Measurements/Component Compliance

Compliance	Description	Data	Compliance	Description	Data