

Access Compliance Report Public Rights-of-Way (Curb Ramps)



8

 Main Street: WARREN_ST
 Cross Street: PALM_DR
 Location:
 NE

ADA ID: RPAT210917104907 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass

Overall Compliance: No

Severity Score:

Codes/Mitigation Info/Possible Solution

	Codes/Milligation into/i
	AND THE PROPERTY OF THE PARTY O
	E. Marie Control of the Control of t
6.	MOR .

Possible Solutions:

Remove & Replace Curb Ramp With Two New
Directional Ramps or Equivalent. Remove &
Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.5.3, R304.2.1, R304.2.3, STD 1115

Total Cost: \$ 6412

Parcel ID Number	340-113-28	Street 1 Name	WARREN_ST
Ramp Island Or Median	None	Stop Condition-Street 1	StopSign
Ramp Orientation	Diag	Street 2 Name	PALM_DR
Google Street View Link:		Stop Condition-Street 2	NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.88359178,-117.84765035

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Com	pliance Description	<u>Data</u>
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A	J		N/A



	Field Measurements/Component Compliance								
1	Com	pliance Description	Data	Com	pliance	Description	Data		
	N/A	Ramp Length (in)	48	N/A	Flare Ty	pe LT			
	Yes	Ramp Width (in)	48				Sloped		
	Yes	Ramp Run Slope (%)	8.1	No	Flare Slo	ope LT (%)	10.5		
	No	Ramp Cross Slope (%)	2.4	N/A	Flare Tra	aversable LT	Yes		
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT			
	N/A	Landing Length (in)	36				Sloped		
	Yes	Landing Width (in)	48	Yes	Flare Slo	ope RT (%)	5.9		
	Yes	Landing Run Slope (%)	1.8	N/A	Flare Tra	aversable RT	Yes		
	No	Landing Cross Slope (%)	3.1	Yes	DWS Pr	ovided	Yes		
	N/A	Landing Movement Obstructed?	Yes	Yes	DWS Co	ontrast	Yes		
		Landing Movement Type	Curb	Yes	DWS Le	ngth (in)	36		
	N/A	Landing Shared	No	Yes	DWS Fu	ll Width	Yes		
	N/A	Clear Space	Yes	Yes	DWS Of	fset Left (in)	0		
	N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Of	fset Right (in)	N/A		
2	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No		
		Crossing 1 Direction	W		Crossing	g 2 Direction	S		
-		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A		
ı	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A		
١		Crossing 1 Slope (%)	8.0		Crossing	g 2 Slope (%)	6		
ı		Crossing 1 Cross Slope (%)	3.9		Crossing	g 2 Cross Slope (%)	0.7		
	Yes	Gutter Ponding	No	No	Curb Slo	ope	11.2		
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	4.9		
	Yes	Gutter Run Slope (%)	0.6		Road Cr	oss Slope (%)	2.7		
	No	Gutter Cross Slope (%)	3.9						
1	Yes	Overall Surface Condition: Accep	ptable	Yes	Perp Joi	int Present	Yes		
		Cross Gutter Present?	Yes		Spandre	l Present?	Yes		
١		Replace Cross Gutter?	No		Replace	Spandrel?	No		