



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



|                                         |                    |                            |                                         |                 |     |
|-----------------------------------------|--------------------|----------------------------|-----------------------------------------|-----------------|-----|
| Main Street: HAMER_DR                   |                    | Cross Street: SHADBURN_AVE |                                         | Location:       | NW  |
| ADA ID: RPAT210917125641                | Ramp Type: No Ramp | Initial Pass/Fail: N/A     | Overall Compliance: No                  | Severity Score: | 100 |
| Codes/Mitigation Info/Possible Solution |                    |                            | Field Measurements/Component Compliance |                 |     |



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A


OC Std/PROW:

STD 1115

Total Cost: \$ 3080

|                          |            |                         |              |
|--------------------------|------------|-------------------------|--------------|
| Parcel ID Number         | 336-503-02 | Street 1 Name           | HAMER_DR     |
| Ramp Island Or Median    | N/A        | Stop Condition-Street 1 | N/A          |
| Ramp Orientation         | N/A        | Street 2 Name           | SHADBURN_AVE |
| Google Street View Link: |            | Stop Condition-Street 2 | N/A          |

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.89268349,-117.84928701](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.89268349,-117.84928701)



| Compliance | Description | Data | Compliance | Description | Data |
|------------|-------------|------|------------|-------------|------|
|            |             |      |            |             |      |