



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: N/A Cross Street: CARBON_CANYON_RD Location: SW

ADA ID: RPAT210920131338 Ramp Type: Type 1 - Perpendicular Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution **Field Measurements/Component Compliance**



Possible Solutions:
Remove & Replace Curb Slope.

Surveyor Notes:
N/A

OC Std/PROW:
R304.2.2, STD 1115

Total Cost: \$ 252

Parcel ID Number: **322-031-23**
 Ramp Island Or Median: **None**
 Ramp Orientation: **NonDiag**
 Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.92226607,-117.83712633

Street 1 Name: N/A
 Stop Condition-Street 1: **Signal**
 Street 2 Name: **CARBON_CANYON_RD**
 Stop Condition-Street 2: N/A

Obstruction and Utility Measurement/Component Compliance			
Compliance	Description	Data	Compliance Description
Yes	Obstructions Present?	No	N/A Utilities Present?
	Obstruction Types	N/A	Utility Types
	Obstruction Dimensions	N/A	

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	95	N/A	Flare Type LT	
Yes	Ramp Width (in)	60			Sloped
Yes	Ramp Run Slope (%)	6.7	N/A	Flare Slope LT (%)	5.5
Yes	Ramp Cross Slope (%)	1.6	N/A	Flare Traversable LT	No
N/A	Landing Present	Yes	N/A	Flare Type RT	
N/A	Landing Length (in)	61			Sloped
Yes	Landing Width (in)	60	Yes	Flare Slope RT (%)	8.1
Yes	Landing Run Slope (%)	1	N/A	Flare Traversable RT	Yes
Yes	Landing Cross Slope (%)	1.8	Yes	DWS Provided	Yes
N/A	Landing Movement Obstructed?	Yes	Yes	DWS Contrast	Yes
	Landing Movement Type	Control Box	Yes	DWS Length (in)	36
N/A	Landing Shared	No	Yes	DWS Full Width	Yes
N/A	Clear Space	N/A	Yes	DWS Offset Left (in)	0
N/A	Clear Space To Crosswalk (in)	N/A	Yes	DWS Offset Right (in)	N/A
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	N/A
	Crossing 1 Direction	E		Crossing 2 Direction	N/A
	Marked Crosswalk 1 Width (in)	120		Marked Crosswalk 2 Width (in)	N/A
Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	1.7		Crossing 2 Slope (%)	N/A
	Crossing 1 Cross Slope (%)	3.3		Crossing 2 Cross Slope (%)	N/A
Yes	Gutter Ponding	No	No	Curb Slope	6.1
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
Yes	Gutter Run Slope (%)	1.1		Road Cross Slope (%)	N/A
Yes	Gutter Cross Slope (%)	1.1			
Yes	Overall Surface Condition:	Acceptable	Yes	Perp Joint Present	Yes
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

