

# Access Compliance Report Public Rights-of-Way (Curb Ramps)

**Main Street:** LINCOLN\_AVE **Cross Street:** N\_PAMPAS\_ST **Location:** NE

**ADA ID:** RPAT210924085132 **Ramp Type:** No Ramp **Initial Pass/Fail:** N/A **Overall Compliance:** No **Severity Score:** 100

**Codes/Mitigation Info/Possible Solution** **Field Measurements/Component Compliance**



**Possible Solutions:**  
Provide Curb Ramp

**Surveyor Notes:**  
N/A

**OC Std/PROW:**  
STD 1115

**Total Cost:** \$ 3080

Compliance	Description	Data	Compliance	Description	Data

Parcel ID Number	<b>360-011-15</b>	Street 1 Name	LINCOLN_AVE
Ramp Island Or Median	N/A	Stop Condition-Street 1	N/A
Ramp Orientation	N/A	Street 2 Name	N_PAMPAS_ST
Google Street View Link:		Stop Condition-Street 2	N/A

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.83497671,-117.85946872](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.83497671,-117.85946872)

