



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: S_RANCHO_SANTIAGO_BLVD		Cross Street: CENTER_ST		Location:	SW
ADA ID: RPAT210928093823	Ramp Type: Type 4 - Parallel	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score:	25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		



Possible Solutions:

Remove & Replace Landing. Remove & Replace Gutter. Relocate Obstruction.

Surveyor Notes:

N/A

OC Std/PROW:

R304.5.3, R302.3, R402.2, STD 1115

Total Cost: \$ 5783

Parcel ID Number 383-271-23
Ramp Island Or Median None
Ramp Orientation Diag
Google Street View Link:

Street 1 Name S_RANCHO_SANTIAGO_BLVD
Stop Condition-Street 1 NoControl
Street 2 Name CENTER_ST
Stop Condition-Street 2 StopSign

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78947328,-117.80142407

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
No	Obstructions Present?	Yes	N/A	Utilities Present?	No
	Obstruction Types	Power Pole		Utility Types	
	Obstruction Dimensions	N/A			N/A

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	117	N/A	Ramp Length RT (in)	82
Yes	Ramp Width LT (in)	48	Yes	Ramp Width RT (in)	49
Yes	Ramp Run Slope LT (%)	8.1	Yes	Ramp Run Slope RT (%)	0.3
Yes	Ramp Cross Slope LT (%)	1.1	Yes	Ramp Cross Slope RT (%)	0.5
N/A	Landing Present	Yes	Yes	DWS Provided	Yes
N/A	Landing Length (in)	48	Yes	DWS Contrast	Yes
Yes	Landing Width (in)	49	Yes	DWS Length (in)	36
Yes	Landing Run Slope (%)	1.2	Yes	DWS Full Width	Yes
No	Landing Cross Slope (%)	5.5		DWS Offset Type	Single
N/A	Landing Movement Obstructed?	No	Yes	DWS Offset Left (in)	0
	Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A
N/A	Landing Shared	No			
N/A	Clear Space	Yes			
N/A	Clear Space To Crosswalk (in)	48			
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
	Crossing 1 Direction	E		Crossing 2 Direction	N
	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	6		Crossing 2 Slope (%)	3.2
	Crossing 1 Cross Slope (%)	1.1		Crossing 2 Cross Slope (%)	6.4
Yes	Gutter Ponding	No	Yes	Curb Slope	0.9
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	3.6
Yes	Gutter Run Slope (%)	2.7		Road Cross Slope (%)	6.4
No	Gutter Cross Slope (%)	4.9	Yes	Perpendicular Joint Present	Yes
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

