

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: E_CENTER_ST **Cross Street: HEWES ST** Location: NW

ADA ID: RPAT210929093125 Ramp Type: Type 4 - Parallel **Initial Pass/Fail: Pass Overall Compliance: No Severity Score:** 6

Codes/Mitigation Info/Possible Solution



Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove &

Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.5.3, R304.5.4, STD 1115

Total Cost: 4252

Parcel ID Number	093-103-29	Street 1 Name	E_CENTER_ST
Ramp Island Or Median	None	Stop Condition-Street 1	StopSign
Ramp Orientation	Diag	Street 2 Name	HEWES_ST
Google Street View Link:		Stop Condition-Street 2	NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78964165,-117.80584154

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data Compliance Description	Data
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A



Field Measurements/Component Compliance								
	Compliance Description		Data	Compliance Description		Data		
,	N/A	Ramp Length LT (in)	70	N/A	Ramp Length RT (in)	118		
	Yes	Ramp Width LT (in)	61	Yes	Ramp Width RT (in)	71		
	Yes	Ramp Run Slope LT (%)	4	Yes	Ramp Run Slope RT (%)	6.7		
	Yes	Ramp Cross Slope LT (%)	0.6	Yes	Ramp Cross Slope RT (%)	0.2		
	N/A	Landing Present	Yes	Yes	DWS Provided	Yes		
	N/A	Landing Length (in)	63	Yes	DWS Contrast	Yes		
	Yes	Landing Width (in)	48	Yes	DWS Length (in)	36		
	Yes	Landing Run Slope (%)	8.0	Yes	DWS Full Width	Yes		
	No	Landing Cross Slope (%)	2.1		DWS Offset Type	Single		
	N/A	Landing Movement Obstructed?	No	Yes	DWS Offset Left (in)	0		
		Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A		
	N/A	Landing Shared	No					
	N/A	Clear Space	Yes					
	N/A	Clear Space To Crosswalk (in)	48					
4252	N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	No		
		Crossing 1 Direction	S		Crossing 2 Direction	E		
R_ST		Marked Crosswalk 1 Width (in)	120		Marked Crosswalk 2 Width (in)	N/A		
Sign	Yes	Ramp Inside Crosswalk 1	Yes	N/A	Ramp Inside Crosswalk 2	N/A		
S_ST		Crossing 1 Slope (%)	2.4		Crossing 2 Slope (%)	5		
ntrol		Crossing 1 Cross Slope (%)	1.2		Crossing 2 Cross Slope (%)	0.9		
	Yes	Gutter Ponding	No	No	Curb Slope	9.6		
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	3.2		
	No	Gutter Run Slope (%)	5.8		Road Cross Slope (%)	1.8		
Data	No	Gutter Cross Slope (%)	2.5	Yes	Perpendicular Joint Present	Yes		
No	Yes	Overall Surface Condition Accep	otable					
NI/A		Cross Gutter Present?	No		Spandrel Present?	No		
N/A		Replace Cross Gutter?	N/A	l	Replace Spandrel?	N/A		