




Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: LORETTA_DR		Cross Street: LORETTA_DR		Location:	SE
ADA ID: RPAT210930095858	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score:	100
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

\$ 3080

Parcel ID Number **395-244-08**
Ramp Island Or Median **N/A**
Ramp Orientation **N/A**
Google Street View Link:

Street 1 Name

LORETTA_DR

Stop Condition-Street 1

N/A

Street 2 Name

LORETTA_DR

Stop Condition-Street 2

N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.76850689,-117.82530638

Compliance	Description	Data	Compliance	Description	Data
------------	-------------	------	------------	-------------	------

