Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Main Street: FIESTA_WAY | **Cross Street: HOWLAND_WAY** | **Location: SE**

ADA ID: RPAT211004151313 | **Ramp Type: Type 6 - Directional 1** | **Initial Pass/Fail: Fail** | **Overall Compliance: No** | **Severity Score: 5**

Codes/Mitigation Info/Possible Solution

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.5.1, STD 1115

Total Cost: **$ 3080**

Parcel ID Number	**401-413-12**	Street 1 Name	**FIESTA_WAY**
Ramp Island Or Median	**None**	Stop Condition-Street 1	**NoControl**
Ramp Orientation	**Diag**	Street 2 Name	**HOWLAND_WAY**
Google Street View Link:		Stop Condition-Street 2	**NoControl**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.75698547,-117.81946284

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	**No**	**N/A**	Utilities Present?	**No**
	Obstruction Types	**N/A**		Utility Types	
	Obstruction Dimensions	**N/A**			**N/A**

Field Measurements/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	**92**	**N/A**	Flare Type LT	
No	Ramp Width (in)	**44**			**N/A**
Yes	Ramp Run Slope (%)	**4.5**	**N/A**	Flare Slope LT (%)	**N/A**
Yes	Ramp Cross Slope (%)	**1.3**	**N/A**	Flare Traversable LT	**N/A**
N/A	Grade Break	**N/A**	**N/A**	Flare Type RT	
N/A	Grade Break Slope (%)	**N/A**			**N/A**
N/A	Grade Break Cross Slope (%)	**N/A**	**N/A**	Flare Slope RT (%)	**N/A**
	Addl Para Ramp Left?	**No**	**N/A**	Flare Traversable RT	**N/A**
	Addl Para Ramp Right?	**No**	**N/A**	DWS Provided	**N/A**
N/A	Landing Present	**N/A**	**N/A**	DWS Contrast	**N/A**
N/A	Landing Length (in)	**N/A**	**N/A**	DWS Length (in)	**N/A**
N/A	Landing Width (in)	**N/A**	**N/A**	DWS Full Width	**N/A**
N/A	Landing Run Slope (%)	**N/A**		DWS Offset Type	**N/A**
N/A	Landing Cross Slope (%)	**N/A**	**N/A**	DWS Left Offset (in)	**N/A**
N/A	Landing Movement Obstructed?	**N/A**	**N/A**	DWS Right Offset (in)	**N/A**
	Landing Movement Type	**N/A**			
N/A	Landing Shared	**N/A**			
N/A	Marked Crosswalk 1	**No**	**N/A**	Clear Space	**Yes**
	Crossing 1 Direction	**N**	**N/A**	Clear Space To Crosswalk (in)	**N/A**
	Marked Crosswalk 1 Width (in)	**N/A**			
N/A	Ramp Inside Crosswalk 1	**N/A**			
	Crossing 1 Slope (%)	**1**			
	Crossing 1 Cross Slope (%)	**0.5**			
N/A	Gutter Ponding	**N/A**	**N/A**	Curb Slope	**9.4**
Yes	Gutter Lip Height (in)	**0**		Road Run Slope (%)	**0.1**
N/A	Gutter Run Slope (%)	**N/A**		Road Cross Slope (%)	**0.5**
N/A	Gutter Cross Slope (%)	**N/A**		Parallel Ramp Side	**N/A**
Yes	Overall Surface Condition	**Acceptable**	**Yes**	Perp Joint Present	**Yes**
	Cross Gutter Present?	**No**		Spandrel Present?	**Yes**
	Replace Cross Gutter?	**N/A**		Replace Spandrel?	**No**