




# Access Compliance Report Public Rights-of-Way (Curb Ramps)



|                                         |                    |                        |                                         |                 |     |
|-----------------------------------------|--------------------|------------------------|-----------------------------------------|-----------------|-----|
| Main Street: ERVIN_LN                   |                    | Cross Street: ERVIN_LN |                                         | Location:       | NW  |
| ADA ID: RPAT211007125543                | Ramp Type: No Ramp | Initial Pass/Fail: N/A | Overall Compliance: No                  | Severity Score: | 100 |
| Codes/Mitigation Info/Possible Solution |                    |                        | Field Measurements/Component Compliance |                 |     |



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

\$ 3080

|                          |            |                         |          |
|--------------------------|------------|-------------------------|----------|
| Parcel ID Number         | 395-454-05 | Street 1 Name           | ERVIN_LN |
| Ramp Island Or Median    | N/A        | Stop Condition-Street 1 | N/A      |
| Ramp Orientation         | N/A        | Street 2 Name           | ERVIN_LN |
| Google Street View Link: |            | Stop Condition-Street 2 | N/A      |

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.76337281,-117.80780678](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.76337281,-117.80780678)



| Compliance | Description | Data | Compliance | Description | Data |
|------------|-------------|------|------------|-------------|------|
|            |             |      |            |             |      |