

Access Compliance Report Public Rights-of-Way (Curb Ramps)



16

Main Street: HICKORY BRANCH RD **Cross Street: BLUEBERRY WAY** Location: NW

ADA ID: RPAT211008145422 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass

Overall Compliance: No Severity Score:

Codes/Mitigation Info/Possible Solution

Possible Solutions: Install Landing. Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R304.5.4, STD 1115

Total Cost: 783

Parcel ID Number		Street 1 Name	HICKORY_BRANCH_RD
Ramp Island Or Median	None	Stop Condition-Street 1	NoControl
Ramp Orientation	Diag	Street 2 Name	BLUEBERRY_WAY
Google Street View Link:		Stop Condition-Street 2	NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.74098338,-117.80076629

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Compliance Description	Data
Yes	Obstructions Present?	No	N/A Utilities Present?	No
	Obstruction Types	N/A	Utility Types	
	Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance								
Com	pliance Description	Data	Com	pliance	Description	Data		
N/A	Ramp Length (in)	74	N/A	Flare Ty	pe LT			
Yes	Ramp Width (in)	49				Sloped		
Yes	Ramp Run Slope (%)	8	N/A	Flare Slo	ppe LT (%)	3.2		
Yes	Ramp Cross Slope (%)	1.8	N/A	Flare Traversable LT		No		
N/A	Landing Present	No	N/A	A Flare Type RT				
N/A	Landing Length (in)	N/A				Sloped		
No	Landing Width (in)	N/A	N/A	Flare Slo	ppe RT (%)	5.7		
No	Landing Run Slope (%)	N/A	N/A	Flare Tra	aversable RT	No		
No	Landing Cross Slope (%)	N/A	Yes	DWS Pr	ovided	Yes		
N/A	Landing Movement Obstructed?	No	Yes	DWS Co	ontrast	Yes		
	Landing Movement Type	N/A	Yes	DWS Le	ngth (in)	36		
N/A	Landing Shared	N/A	Yes	DWS Fu	ll Width	Yes		
N/A	Clear Space	Yes	Yes	DWS Of	fset Left (in)	0		
N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Of	fset Right (in)	N/A		
N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No		
	Crossing 1 Direction	S		Crossing	2 Direction	E		
	Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A		
N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A		
	Crossing 1 Slope (%)	4.7		Crossing	g 2 Slope (%)	5.2		
	Crossing 1 Cross Slope (%)	1.1		Crossing	g 2 Cross Slope (%)	1.9		
Yes	Gutter Ponding	No	Yes	Curb Slo	рре	3.4		
Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	0.8		
No	Gutter Run Slope (%)	5.9		Road Cr	oss Slope (%)	4.9		
Yes	Gutter Cross Slope (%)	0.2						
Yes	Overall Surface Condition: Accep	ptable	Yes	Perp Joi	nt Present	Yes		
	Cross Gutter Present?	No		Spandre	I Present?	No		
	Replace Cross Gutter?	N/A		Replace	Spandrel?	N/A		