Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

Main Street: WOODLAWN_AVE | **Cross Street:** LUCINDA_WAY | **Location:** W

ADA ID: RPAT211012143043 | **Ramp Type:** No Ramp | **Initial Pass/Fail:** N/A | **Overall Compliance:** No | **Severity Score:** 100

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost: **$ 3080**

Parcel ID Number	103-152-09	Street 1 Name	WOODLAWN_AVE
Ramp Island Or Median	N/A	Stop Condition-Street 1	N/A
Ramp Orientation	N/A	Street 2 Name	LUCINDA_WAY
Google Street View Link:		Stop Condition-Street 2	N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.7536976,-117.79888868

Field Measurements/Component Compliance

Compliance	Description	Data	Compliance	Description	Data