




Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: LEAFWOOD_LN		Cross Street: LEAFWOOD_LN		Location:	SW
ADA ID: RPAT211018150512	Ramp Type: No Ramp	Initial Pass/Fail: N/A	Overall Compliance: No	Severity Score:	100
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

OC Std/PROW:

STD 1115

Total Cost:

\$ 3080

Parcel ID Number 395-282-10

Ramp Island Or Median N/A

Ramp Orientation N/A

Google Street View Link:

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.76546312,-117.82130812

Street 1 Name LEAFWOOD_LN

Stop Condition-Street 1 N/A

Street 2 Name LEAFWOOD_LN

Stop Condition-Street 2 N/A

Compliance	Description	Data	Compliance	Description	Data
------------	-------------	------	------------	-------------	------

